



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION IV  
1600 EAST LAMAR BOULEVARD  
ARLINGTON, TEXAS 76011-4511

March 19, 2018

Mr. Mark E. Reddemann  
Chief Executive Officer  
Energy Northwest  
P.O. Box 968  
Richland, WA 99352-0968

SUBJECT: COLUMBIA GENERATING STATION – NRC SECURITY INSPECTION  
REPORT 05000397/2018410

Dear Mr. Reddemann:

On February 14, 2018, the U.S. Nuclear Regulatory Commission (NRC) completed a security inspection at your Columbia Generating Station. The NRC inspectors discussed the results of this inspection with Mr. T. Phelps, Security Operations Supervisor, and other members of your staff. The results of this inspection are documented in the enclosed report.

The inspection examined activities conducted under your license as they relate to security and compliance with NRC rules and regulations and with the conditions of your license. The inspectors reviewed selected procedures and records, observed activities, and interviewed personnel.

The NRC inspectors did not identify any finding or violation of more than minor significance.

In accordance with Title 10 of the *Code of Federal Regulations* (10 CFR) 2.390, "Public Inspections, Exemptions, Requests for Withholding," of the NRC's "Rules of Practice and Procedure," a copy of this letter will be available electronically for public inspection in the NRC's Public Document Room or from the Publicly Available Records (PARS) component of the NRC's Agencywide Documents Access and Management System (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

Enclosure transmitted herewith  
contains SUNSI. When separated  
from enclosure, this transmittal  
document is decontrolled.

~~OFFICIAL USE ONLY – SECURITY-RELATED INFORMATION~~

M.E. Reddemann

2

However, the enclosed report contains Security-Related Information in accordance with 10 CFR 2.390(d)(1) and its disclosure to unauthorized individuals could present a security vulnerability. Therefore, the material in the enclosure will not be made available electronically for public inspection in the NRC Public Document Room or from the PARS component of NRC's ADAMS.

Sincerely,

*/RA/*

Mark Haire, Chief  
Project Branch A  
Division of Reactor Projects

Docket No. 50-397  
License No. NPF-21

Enclosure:  
Inspection Report 05000397/2018410

cc w/enclosure:  
Mr. Stephen M. Sullivan II  
Security Operations Manager  
Energy Northwest  
Columbia Generating Station  
PE30, 76 North Power Plant Loop  
Richland, WA 99352

cc w/o encl: Electronic Distribution

~~OFFICIAL USE ONLY – SECURITY-RELATED INFORMATION~~

~~OFFICIAL USE ONLY – SECURITY-RELATED INFORMATION~~

COLUMBIA GENERATING STATION – NRC SECURITY INSPECTION REPORT  
05000397/2018410 – DATED MARCH 19, 2018

**Distribution w/enclosure:**

EWharton, NSIR  
NSimonian, NSIR  
DGarner, NSIR  
RMcKinley, RI DRS  
BDesai, RII DRS  
SOrth, RIII DRS  
KKennedy, ORA  
SMorris, ORA  
TPruett DRP  
RLantz, DRP  
AVegel, DRS  
JClark, DRS  
JGroom, DRS  
MHaire, DRP  
RAlexander, DRP  
GKolcum, DRP  
LBrandt, DRP  
MBennett, DRP

**Distribution w/o enclosure:**

VDricks, ORA  
JKlos, NRR  
EUribe, DRS/IPAT  
MHerrera, FRMB  
SKirkwood, RC  
EUribe, DRS  
JWeil, RIV/CAO  
AMoreno RIV/CAO  
JBowen, RIV/OEDO  
ACES  
GWalker, OI  
BMaier, ORA  
RidsOeMailCenter Resource

ADAMS ACCESSION NUMBER (ENTIRE REPORT): ML18078B280

SUNSI Review: ADAMS:  Non-Publicly Available  Non-Sensitive Keyword:  
By: MSH2  Yes  No  Publicly Available  Sensitive MD 3.4.A.3

ADAMS ACCESSION NUMBER (COVER LETTER ONLY): ML18078B273

SUNSI Review: ADAMS:  Non-Publicly Available  Non-Sensitive Keyword:  
By: MSH2  Yes  No  Publicly Available  Sensitive NRC-002

OFFICE	SRI:DRP/A	C:DRS/PSB1	SPE:DRP/A	BC:DRP/A	
NAME	GKolcum	JGroom	RAlexander	MHaire	
SIGNATURE	/RA/	/RA/	/RA/	/RA/	
DATE	3/8/18	3/12/18	3/08/18	3/19/18	

OFFICIAL RECORD COPY

~~OFFICIAL USE ONLY – SECURITY-RELATED INFORMATION~~