

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 N J S G S L 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
01 REPORT SOURCE L 6 0 5 0 0 0 2 7 2 7 1 2 0 8 8 0 8 0 3 2 5 8 1 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During routine surveillance testing, it was found that the Nos. 11 and 12 Auxiliary
03 Feedwater Pumps could be stopped from the control console if a Steam Generator low
04 low level signal is received during Safeguards Equipment Control System operation.
05 This is a malfunction of a safety-related system and is a violation of Technical
06 Specification 6.9.1.8.e. No previous occurrences.
07
08

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
C H 11 B 12 A 13 Z Z Z Z Z Z 14 Z 15 Z 16
9 10 11 12 13 18 19 20

17 LER RO REPORT NUMBER EVENT YEAR SHUTDOWN METHOD SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
8 0 21 22 23 0 6 3 24 26 27 0 1 28 29 X 30 1 31 32

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
F 18 X 19 Z 20 Z 21 0 0 0 0 22 Y 23 N 24 Z 25 Z 9 9 9 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Design error. Design Change Request 1-EC-1084 was issued and implemented on
11 December 6, 1980 to preclude manual operation of the Auxiliary Feedwater Pumps
12 during Safeguards Equipment Control System operation for Unit 1. Design Change
13 Request 2-EC-1085 , implemented on February 24, 1981, will accomplish the same for
14 Unit 2.

15 FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)
G 28 0 0 0 29 N/A B 31 Surveillance Test
7 8 9 10 12 13 44 45 46 80

16 ACTIVITY CONTENT RELEASD OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
Z 33 Z 34 N/A N/A
7 8 9 10 11 44 45 80

17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
0 0 0 37 Z 38 N/A
7 8 9 11 12 13 80

18 PERSONNEL INJURIES NUMBER DESCRIPTION (41)
0 0 0 40 N/A
7 8 9 11 12 13 80

19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)
Z 42 N/A
7 8 9 11 12 80

20 PUBLICITY ISSUED DESCRIPTION (45) NRC USE ONLY
N 44 N/A
7 8 9 10 80

104020551 NAME OF PREPARER W. J. Steele PHONE: 609-935-0998