

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N J S G S 1 2 0 0 0 0 0 0 0 0 0 0 0 0 3 4 1 1 1 1 4 5

CON'T REPORT SOURCE L 6 0 5 0 0 0 2 7 2 7 0 3 1 6 8 1 8 0 4 1 5 8 1 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

At 0900 hours on 3/12/81, the Senior Shift Supervisor on shift was requested by maintenance personnel to grant permission to replug several penetration fire barriers. The Senior Shift Supervisor discovered that no fire watches had been established when the plugs were removed on 2/18/81 in accordance with Action Statement 3.7.11 as the Action Statement had not been entered or noted in the log. The plugs were 3-1/2" Welding Lead Plugs designed to retard the heat transferred from a fire on one side of the penetration to the other for a period of three (3) hours.

0 9 SYSTEM CODE A B 11 CAUSE CODE A 12 CAUSE SUBCODE C 13 COMPONENT CODE x x x x x x 14 COMP. SUBCODE x 15 VALVE SUBCODE 7 16

17 LER/RO REPORT NUMBER 8 1 21 EVENT YEAR 8 1 22 SEQUENTIAL REPORT NO. 0 3 0 24 OCCURRENCE CODE 0 3 27 REPORT TYPE L 30 REVISION NO. 0 32 ACTION TAKEN H 18 G 19 FUTURE ACTION G 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED Y 23 NPRD-4 FORM SUB. N 24 PRIME COMP. SUPPLIER L 25 COMPONENT MANUFACTURER G 0 5 1 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

Personnel involved in the removing of the plugs were not familiar with procedures and documentation required. The personnel involved have been counseled. Administrative Procedures are currently being revised to establish more effective administrative control when fire barriers are to be breached.

1 5 FACILITY STATUS E 28 % POWER 1 0 0 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Discovery by Senior Shift Supervisor 32

1 6 ACTIVITY CONTENT Z 33 Z 34 RELEASED OF RELEASE Z 34 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION N/A 39

1 2 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION N/A 41

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43

2 0 ISSUED N 44 DESCRIPTION N/A 45 PUBLICITY NRC USE ONLY NAME OF PREPARER W. J. Steele PHONE: 609-935-0998

8104240548