

(j-11)	LICENSEE EVENT REPORT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	N J S G S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T	REPORT L 6 0 5 0 0 0 2 7 2 7 0 2 1 4 8 1 8 0 5 0 4 8 1 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2	During normal operation on 2/14/81, Diesel Generator 1A was declared inoperable
0 3	because of a cooling water leak. Action Statement 3.8.1.1.a was entered at
0 4	2233 hours. Similar occurrence: 77-77
0 5	L
0 6	L
07	
0 B 7 8	9 SYSTEM CAUSE CAUSE COMP. VALVE
0 9	E E 11 E 12 B 13 P I P E X X 14 A 15 Z 16
	LER RO EVENT YEAR REPORT NO. OCCURRENCE REPORT TYPE NO. OCCURRENCE REPORT TYPE NO. O 1 8 1 21 22 23 24 26 27 28 29 30 31 32
	ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER A 18 Z 19 Z 20 Z 21 0 0 0 0 Y 23 N 24 L 25 X 9 9 9 26
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0	The nipple connecting Jacket Water Valve 1DA45A and the Jacket Water Pipe was
11	cracked and leaking. The nipple was replaced in kind. The Action Statement was
1 2	terminated at 2317 hours on 2/15/81.
1 3	
1 4 7 B	9
15	STATUS ** POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 E 28 1 0 0 29 N/A A 31 Operator Observation 9 10 12 13 44 45 46 80
	CTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY (35) Z (33) Z (34) N/A LOCATION OF RELEASE (36) N/A
17	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 0 0 0 37 Z 38 N/A
18	PERSONNEL INJURIES NUMBER DESCRIPTION 41 0 0 0 40 N/A
19	9 11 12 LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION N/A
7 8	PUBLICITY ISSUED DESCRIPTION 45 N/A 8 10 5 1 40 372 N/A N/A
7 B	9 10 68 69 80 5 NAME OF REFRANCE W. J. Steele 809-935-0998 0