

## UNITED STATES NUCLEAR REGULATORY COMMISSION

WASHINGTON, D.C. 20555

February 9, 1982

MEMORANDUM FOR:

William J. Dircks

Executive Director for Operations

FROM:

Commissioner Roberts

SUBJECT:

SALEM UNITS 1 AND 2 - SPILL OF SPENT FUEL POOL WATER

Please provide the following information regarding the February 1 spill of contaminated water at Salem Units 1 and 2:

1. Was the temporary connection between the Unit 1 and Unit 2 spent fuel pool cooling systems approved by the licensee's onsite and offsite review committees?

シャデカ

- 2. Did the NRC Resident Inspector have the opportunity to review the procedure prior to its use? NO
- 3. In the staff's review of spent fuel pool modifications, has an event such as that occurring at Salem 1 and 2 been considered?
- 4. What steps will be taken to ensure that a similar event does not occur at other operating facilities?

cc: Chairman Palladino
Commissioner Gilinsky
Commissioner Bradford
Commissioner Ahearne
SECY

Rec'd Off. EDO

Time

Time 8/15 A