



180 W Monte Ave, Bloomington, CA 92316

March 06, 2018

Director of NMSS
Attn:GLTS
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

In Fullfillment of the requirements of 10 CFR 31.5 © 8, we hereby notify you that on March 02,2018 we transferred the self-luminous exit signs listed on the attached spredd sheet to SRB Technologies Inc. 2580 Landmark Dr, Winston-Salem, NC 27103 North Carolina License #034-0534-2. As required, for each sign losted on the spreadsheet, we included the name of the manufactureer, model number, and serial number.

If you have any questions, please contact Poli Ortiz at 909-421-2012.

Sincerely,
Poli Ortiz
Facility Manager

A handwritten signature in black ink, appearing to be "Poli Ortiz", written over the typed name.



This Serial Number Log must also accompany each box as a packing slip and so must accurately reflect the inventory of EACH box.

Inventory Box Number: 1 of 5

| Line | Manufacturer Name | Model Number | Serial Number | Date of Manufacture | Activity (Ci or TBq amount) |
|------|----------------------|--------------|---------------|---------------------|-----------------------------|
| 1 | Safety light corp | 2000 | 280401 | 8/2004 | 7.5 |
| 2 | Safety light corp | 2000 | 280368 | 8/2004 | 7.5 |
| 3 | Safety light corp | 2000 | 280376 | 8/2004 | 7.5 |
| 4 | Safety light corp | 2000 | 280398 | 8/2004 | 7.5 |
| 5 | Safety light corp | 2000 | 280400 | 8/2004 | 7.5 |
| 6 | Safety light corp | 2000 | 280399 | 8/2004 | 7.5 |
| 7 | Safety light corp | 2000 | 280393 | 8/2004 | 7.5 |
| 8 | Safety light corp | 2000 | 280369 | 8/2004 | 7.5 |
| 9 | Safety light corp | 2000 | 280397 | 8/2004 | 7.5 |
| 10 | ISO lite Corporation | SLX-60 | H52299 | | 0.465 |

AO
Initial

2-7-2018
Date



This Serial Number Log must also accompany each box as a packing slip and so must accurately reflect the inventory of EACH box.

Inventory Box Number: 2 of 5

| Line | Manufacturer Name | Model Number | Serial Number | Date of Manufacture | Activity (Ci or TBq amount) |
|------|-------------------|--------------|---------------|---------------------|-----------------------------|
| 1 | Safety light corp | 2000 | 294224 | 10/2004 | 7.5 |
| 2 | Safety light corp | 2000 | 294226 | 10/2004 | 7.5 |
| 3 | Safety light corp | 2000 | 280386 | 8/2004 | 7.5 |
| 4 | Safety light corp | 2000 | 280387 | 8/2004 | 7.5 |
| 5 | Safety light corp | 2000 | 280371 | 8/2004 | 7.5 |
| 6 | Safety light corp | 2000 | 280372 | 8/2004 | 7.5 |
| 7 | Safety light corp | 2000 | 280383 | 8/2004 | 7.5 |
| 8 | Safety light corp | 2000 | 280395 | 8/2004 | 7.5 |
| 9 | Safety light corp | 2000 | 294225 | 10/2004 | 7.5 |
| 10 | Safety light corp | 2000 | 280394 | 8/2004 | 7.5 |

AO

Initial

2-7-2018

Date

Please email this log to sales@tritiumdisposal.com or fax to: 614-863-0622.

Make sure to include your contact info if you have not already been assigned a TritiumDisposal account rep.



This Serial Number Log must also accompany each box as a packing slip and so must accurately reflect the inventory of EACH box.

Inventory Box Number: 3 of 5

| Line | Manufacturer Name | Model Number | Serial Number | Date of Manufacture | Activity (Ci or TBq amount) |
|------|-------------------|--------------|---------------|---------------------|-----------------------------|
| 1 | Forever-lite inc. | SLXTUIGW20 | 109285 | 10-2002 | 11.47 |
| 2 | Forever-lite inc. | SLXTUIGW20 | N/A | N/A | 11.47 |
| 3 | Forever-lite inc | SLXTUIGW20 | 104110 | 10-2002 | 11.47 |
| 4 | Forever-lite inc | SLXTUIGW20 | 10928 | 10-2002 | 11.47 |
| 5 | Forever-lite inc | N/A | N/A | 10-2002 | 11.47 |
| 6 | Forever-lite inc | N/A | N/A | N/A | N/A |
| 7 | Forever-lite inc | SLXTUIGW20 | 109282 | 10-2002 | 11.47 |
| 8 | Forever-lite inc | N/A | N/A | N/A | N/A |
| 9 | Forever-lite inc | N/A | N/A | N/A | N/A |
| 10 | Forever-lite inc | N/A | N/A | N/A | N/A |

AO
Initial

2-7-2018
Date

Please email this log to sales@tritiumdisposal.com or fax to: 614-863-0622.
Make sure to include your contact info if you have not already been assigned a TritiumDisposal account rep.



This Serial Number Log must also accompany each box as a packing slip and so must accurately reflect the inventory of EACH box.

Inventory Box Number: 4 of 5

| Line | Manufacturer Name | Model Number | Serial Number | Date of Manufacture | Activity (Ci or TBq amount) |
|------|-------------------|--------------|---------------|---------------------|-----------------------------|
| 1 | Shield Source inc | 101 | T7444 | 10/2003 | 0.278 |
| 2 | Shield Source inc | 101 | T7445 | 10/2003 | 0.278 |
| 3 | Shield Source inc | 101 | T7441 | 10/2003 | 0.278 |
| 4 | Shield Source inc | 101 | T7440 | 10/2003 | 0.278 |
| 5 | Shield Source inc | 101 | T7443 | 10/2003 | 0.278 |
| 6 | Shield Source inc | 101 | T7442 | 10/2003 | 0.278 |
| 7 | Shield Source inc | 101 | T7453 | 10/2003 | 0.278 |
| 8 | Shield Source inc | 101 | T7452 | 10/2003 | 0.278 |
| 9 | Shield Source inc | 101 | T7451 | 10/2003 | 0.278 |
| 10 | Shield Source inc | 101 | T7450 | 10/2003 | 0.278 |

AO
Initial

2-7-2018
Date

Please email this log to sales@tritiumdisposal.com or fax to: 614-863-0622.
Make sure to include your contact info if you have not already been assigned a TritiumDisposal account rep.



This Serial Number Log must also accompany each box as a packing slip and so must accurately reflect the inventory of EACH box.

Inventory Box Number: 5 of 5

| Line | Manufacturer Name | Model Number | Serial Number | Date of Manufacture | Activity (Ci or TBq amount) |
|------|----------------------------|--------------|---------------|---------------------|-----------------------------|
| 1 | Shield Source inc. | SLx60 | Y21076 | 5-2008 | 0.278 |
| 2 | Forever lite inc | SLXTUIGWZ0 | 109283 | N/A | 11.47 |
| 3 | Forever lite inc | N/A | N/A | N/A | N/A |
| 4 | Forever lite inc | N/A | N/A | N/A | N/A |
| 5 | Forever lite inc | SLXTUIGWZ0 | 108487 | 9-2002 | 11.47 |
| 6 | Forever lite inc | SLXTUIGWZ0 | 108170 | 7-2002 | 11.47 |
| 7 | SRB technologies inc | N/A | 287246 | 7-2003 | 20 |
| 8 | SRB technologies inc | N/A | 272682 | 7-2002 | 20 |
| 9 | SRB technologies inc | N/A | 272684 | 7-2002 | 20 |
| 10 | SRB technologies inc | N/A | 272683 | 7-2002 | 20 |

AO
Initial

2-7-2018
Date

Please email this log to sales@tritiumdisposal.com or fax to: 614-863-0622.
Make sure to include your contact info if you have not already been assigned a TritiumDisposal account rep.



180 W Monte Ave, Bloomington, CA 92316

March 06, 2018

**Director of NMSS
Attn:GLTS
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001**

In Fullfillment of the requirements of 10 CFR 31.5 © 8, we hereby notify you that on March 02,2018 we transferred the self-luminous exit signs listed on the attached spredd sheet to SRB Technologies Inc. 2580 Landmark Dr, Winston-Salem, NC 27103 North Carolina License #034-0534-2. As required, for each sign losted on the spreadsheet, we included the name of the manufactureer, model number, and serial number.

If you have any questions, please contact Poli Ortiz at 909-421-2012.

Sincerely,
Poli Ortiz
Facility Manager