

APPENDIX A

NOTICE OF VIOLATION

Public Service Electric and Gas Company
Salem Nuclear Generating Station

Docket Nos. 50-272
50-311

License Nos. DPR-70
DPR-75

As a result of the inspection conducted on March 17, 1990 - April 30, 1990, and in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions", 10 CFR 2, Appendix C (Enforcement Policy 1989), the following violation was identified:

- A. Salem Unit 1 and 2 Technical Specifications 6.8.2, ANSI N18.7 - 1976, and Salem Administrative Procedure No. AP-32 require station procedures to be reviewed every two years.

Contrary to the above, on April 3, 1990, the inspector determined that approximately 27% of the 2922 procedures requiring biennial review had not been reviewed within their two-year review period.

This is a Severity Level IV violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, Public Service Electric and Gas Company is hereby required to submit to this office within 30 days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

9006040333 900524
FDR ADDCK 05000272
PDC