

**From:** [Tobin, Jennifer](#)  
**To:** ["Lashley, Phil H."](#)  
**Subject:** RE: Beaver Valley Follow-Up (re: Relief Request 1-TYP-4-BN-01)  
**Date:** Friday, April 06, 2018 3:19:00 PM

---

Good afternoon Phil,  
Thank you for your email. The NRC has determined that a correction is not needed in the safety evaluation for this relief request regarding the potential for misinterpretation. However, this email will be added to ADAMS to document our communication on this issue for future reference.

Please let me know if you have additional questions or would like to discuss further.

Thank you. I hope you have a wonderful weekend!  
Jenny

**Jenny Tobin**  
**Project Manager**  
**NRR/DORL/LPL-1**  
**Office O9-C12 Phone 301-415-2328**

---

**From:** Lashley, Phil H. [mailto:phlashley@firstenergycorp.com]  
**Sent:** Friday, April 06, 2018 8:42 AM  
**To:** Tobin, Jennifer <Jennifer.Tobin@nrc.gov>  
**Subject:** [External\_Sender] Beaver Valley Follow-Up

Jenny,

As a follow-up to our discussion this morning.

**In FENOC's November 15, 2017 request to extend certain reactor vessel inspections (Request 1-TYP-4-BN-01), the second paragraph in Section 5 states:**

If there is an opportunity to perform examinations due to moving the core support structure from the reactor vessel to the permanent storage stand prior to the 2027 refueling outage, the code required VT-3 examinations will be performed on the core support structure and interior reactor vessel attachments in order to fulfill the exam requirements for the extended interval.

**Section 3.2.6.3 of the safety evaluation states:**

In the request, the licensee stated that BVPS-1 would opportunistically perform the B-N-2 and B-N-3 examinations if the core support structure is removed.

**If the NRC's statement is not taken in context of the licensee request, then it would indicate that the inspections would be performed anytime the core support structure is removed regardless of whether or not it was placed on the stand. We are bringing this to your attention to determine if there is any concern that the threshold as to when the B-N-2 and B-N-3 examinations would be performed is different between the two documents.**

Respectfully,

Phil H. Lashley  
Fleet Licensing Supervisor  
Cell: (330) 696-7208  
Office: (330) 315-6808  
Mail Stop: A-WAC-B1

---

**The information contained in this message is intended only for the personal and confidential use of the recipient(s) named above. If the reader of this message is not the intended recipient or an agent responsible for delivering it to the intended recipient, you are hereby notified that you have received this document in error and that any review, dissemination, distribution, or copying of this message is strictly prohibited. If you have received this communication in error, please notify us immediately, and delete the original message.**