



Public Service Electric and Gas Company P.O. Box 236 Hancocks Bridge, New Jersey 08038-0236

Nuclear Business Unit

MAY 12 1998
LR-N980226

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

LER 272/98-004-00
SALEM GENERATING STATION - UNIT 1
FACILITY OPERATING LICENSE NO. DPR-70
DOCKET NO. 50-272

Gentlemen:

This Licensee Event Report entitled "Failure To Perform Radioactive Effluent Concentration Surveillance And Effluent Monitoring Instrument Channel Setpoint Determinations In Accordance With Technical Specifications" was originally submitted on April 1, 1998. In that report, on page 4 of 5, Licensee Event Report 311/97-007-00 was incorrectly referenced as a related occurrence in the Prior Similar Occurrences section. The actual prior similar occurrence was Licensee Event Report 272/97-007-00. This letter resubmits LER 272/98-004-00 with page 4 of 5 amended to reflect the correct Licensee Event Report number.

Should you have any questions regarding this submittal, please contact R. B. Knieriem at (609) 339-1782.

Sincerely,

D. R. Powell
Director -
Licensing/Regulation and Fuels

Attachment

/rbk

C Distribution
LER File 3.7
9805210266 980512
PDR ADOCK 05000272
S PDR
The power is in your hands.

JE 22 11