



PSE&G

Public Service Electric and Gas Company P.O. Box 236 Hancocks Bridge, New Jersey 08038-0236

Nuclear Business Unit

JAN 07 1999

LR-N980601

United States Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Gentlemen:

**TRANSMITTAL OF THE SALEM UNIT 2
INSERVICE INSPECTION PROGRAM (REVISION 1B)
SALEM UNIT 2
DOCKET NO. 50-311
FACILITY OPERATING LICENSE NO. DPR-75**

By this letter PSE&G transmits the Salem Unit 2 Inservice Inspection Program (Revision 1B).

Salem Unit 2's Inservice Inspection Program (page 1-2) presently requires the ISI Program Long Term Plan to be revised at the end of each Inspection Period. This period revision is also required to be submitted to the NRC. Revision 1B deletes this requirement, and states the following (see page 1-2 for change):

"This document is subject to revisions, due to plant modifications and/or changes in the Regulatory and augmented requirements etc. The initial issue was transmitted to the NRC by letter, however all future ISI Program Plan revisions will be available for review at the plant site."

This approach, which helps to reduce the paper work burdens on both the NRC and PSE&G, has been implemented in both the Salem Unit 1, Hope Creek and other nuclear facility ISI programs. Revision 1B also incorporates the following additional changes:

1. Incorporated the new IVVI Program into the ISI LTP.
2. Corrected miscellaneous spelling errors & typos.
3. Revised references to IWE & IWL IAW 10CFR50.55a NRC rule making.
4. Changed references to Code Cases from N-401 & N-402 to N-401-1 & N-402-1 IAW the S/G Group request.
5. Added reference to Code Case N-532.

9901210093 990107
PDR ADOCK 05000311
G PDR

A0471/0

The power is in your hands.

JAN 07 1999


Document Control Desk
LR-N980601

-2-

6. Added 2.5(f) - Substitution of Section XI, paragraph IWA-5250 with the 1990 Addenda.
7. Table 8-1 - Deleted NRC IEB 82-02 and revised 88-08 requirements and added NRC IEB 7913, 93-20 & 90-04.
8. Section 9.0, deleted references to hydrostatic testing.
9. Added note to the 3rd paragraph of Section 10.0.
10. Added Relief Request RR-A1, RR-A2 & RR-A3.
11. Added WinISI (ISI data base program) status codes to Section 15.0, paragraph 15.1 (F).
12. Added a paragraph to Table 15-1, paragraph IV, "Supports other than piping supports".
13. Revised all Relief Requests to include an NRC Approved/Date block.
14. Added reference to Category C-G to the 2nd to the last paragraph of page 15-8, to properly reflect the Code.

Should there be any questions with regard to this submittal, please do not hesitate to contact us.

Sincerely,



D. R. Powell
Director -
Licensing / Regulation and Fuels

JAN 07 1999

Document Control Desk
LR-N980601

-3-

Enclosure (1)

C Mr. Hubert J. Miller, Administrator - Region I
U. S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Mr. P. Milano, Licensing Project Manager - Salem
U. S. Nuclear Regulatory Commission
One White Flint North
11555 Rockville Pike
Mail Stop 14E21
Rockville, MD 20852

Mr. S. Morris - Salem (S09)
USNRC Senior Resident Inspector

Mr. K. Tosch, Manager, IV
NJ Department of Environmental Protection
Division of Environmental Quality
Bureau of Nuclear Engineering
CN 415
Trenton, NJ 08625

Raymond Snyder
Department of Community Affairs
P. O. Box 814
Trenton, New Jersey 08625