

Letter to N. C. Moseley from Florida Power and Light Company dated April 28, 1975.

Letter to N. C. Moseley from Florida Power and Light Company dated April 23, 1975.

DISTRIBUTION:

50-335

H. D. Thornburg, IE

IE:HQS (5)

Office of Standards Development

Central Files

Division of Reactor Licensing (13)

PDR


Local PDR

NSIC

TIC

STATE

Misc 



April 28, 1975
L-75-200

Mr. Norman C. Moseley, Director
Office of Inspection and Enforcement, Region II
U. S. Nuclear Regulatory Commission
230 Peachtree Street, N. W., Suite 818
Atlanta, Georgia 30303

Dear Mr. Moseley:

Re: Crane Counterweight Drop,
St. Lucie Unit No. 1
(Control No. H00556F2)


My letter to Mr. Donald F. Knuth of the Nuclear Regulatory Commission, dated February 21, 1975, indicated that a final report of the subject incident would be submitted by May 22, 1975. FPL believes that no meaningful final report can be presented until the repairs to the Reactor Auxiliary Building are completed. This is expected to be done in 3 - 4 months. Accordingly, FPL requests postponement of the final report until September 5, 1975. This has been discussed with Mr. L. E. Foster of your office and approved by him on April 28, 1975.

Yours very truly,

Robert E. Uhrig
Vice President

REU:tg

cc: Jack R. Newman, Esq.



April 23, 1975
L-75-197

Mr. Norman C. Moseley, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
230 Peachtree Street, N. W., Suite 818
Atlanta, Georgia 30303

Dear Mr. Moseley:

Re: Time Extension for Reports due under
10 CFR 50.55 (e)

In my letter of January 24, 1975, to you, I forwarded an interim report in accordance with 10 CFR 50.55 (e) concerning a crack discovered in the east wall of the refueling canal of St. Lucie Unit No. 1. (Refer to Control No. H00480F2.) I indicated to you that a final report on this matter would be submitted in 60 - 90 days. On March 26, 1975, I reported an incident to you concerning failure of Square D Control Relays installed on the 1A diesel generator at St. Lucie Unit No. 1 and advised you that an interim report would be forwarded to the Nuclear Regulatory Commission by April 23, 1975.

Florida Power & Light Company hereby requests an extension of time for submission of these reports as shown below:

Refueling Canal Wall Crack - May 8, 1975
Failure of Square D Control Relays - May 7, 1975

This request has been discussed with Mr. L. E. Foster of your office and confirmed by him. The extension of time is required because of the failure of our architect-engineer to respond to our requests for this information in a timely manner.

Yours very truly,

Robert E. Uhrig
Vice President

REU:LLL:tg

cc: Jack R. Newman, Esq..