

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

TO: N.C. MOSELEY.

FROM: FLORIDIA PWR & LIGHT CO.
MIAMI, FL.
A.D. SCHMIDT

DATE OF DOCUMENT
3/24/77

DATE RECEIVED
4/6/77

LETTER
 ORIGINAL
 COPY

NOTORIZED
 UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED
1 signed

DESCRIPTION
LTR. TRANS THE FOLLOWING

(1P)

PLANT NAME: ST LUCIE # 1

SAB

ENCLOSURE
LICENSEE EVENT REPORT FOR R.O. # 77-12, ON
2/24/77 CONCERNING THE DIGITAL DATA PROCESSING
SYSTEM MALFUNCTIONING.....

(2P)

ACKNOWLEDGED
DO NOT REMOVE

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION

BRANCH CHIEF:	<i>Ziemann</i>
W/3 CYS FOR ACTION	
LIC. ASST.:	<i>Diggs</i>
W/ CYS	
ACRS (6 CYS HOLDING/SENT	<i>As CAT B</i>

INTERNAL DISTRIBUTION

<input checked="" type="checkbox"/> REG FILE				
NRC PDR				
I & E (2)				
MIPC				
SCHROEDER/IPPOLITO				
HOUSTON				
NOVAK/CHECK				
GRIMES				
CASE				
BUTLER				
HANAUER				
TEDESCO/MACCARY				
EISENHUT				
BAER				
SHAO				
VOLLMER/BURGH				
KREGER/J. COLLINS				

EXTERNAL DISTRIBUTION

LPDR: <i>K + Pierce, K la</i>	
TIC:	
NSIC:	

CONTROL NUMBER

104
770980235 (A)

1944

MEMORANDUM FOR THE RECORD
DATE: 10/10/44
SUBJECT: [Illegible]

1944


MEMORANDUM FOR THE RECORD
DATE: 10/10/44
SUBJECT: [Illegible]

..... NEW YORK

[Illegible]


[Illegible]

[Illegible]



March 24, 1977

PRN-LI-77-83



Mr. Norman C. Moseley, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
230 Peachtree Street, N. W., Suite 1217
Atlanta, Georgia 30303

Regulatory

File Copy

Dear Mr. Moseley:

REPORTABLE OCCURRENCE 335-77-12
ST. LUCIE UNIT 1
DATE OF OCCURRENCE: FEBRUARY 24, 1977

DIGITAL DATA PROCESSING SYSTEM

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.

Very truly yours,


J.R. Bensen
A. D. Schmidt
Vice President
Power Resources


MAS/cpc

Attachment

cc: Robert Lowenstein, Esquire
Director, Office of Inspection and Enforcement (30)
Director, Office of Management Information and
Program Control (3)

770980235





Licensee Event Report
Reportable Occurrence 335-77-12
Page 2 of 2

EVENT DESCRIPTION (Continued)

indication channels operable. This is the sixth reportable occurrence involving loss of the DDPS (335-76-19, 335-76-27, 335-76-38, 335-76-48, 335-77-9), but the first occurrence due to this cause (335-77-12).

CAUSE DESCRIPTION (Continued)

computer anomalies of this sort are not uncommon. Auto-restart of the unit functioned properly (after cause of halt was discovered) and the DDPS was back in service 18 minutes after the halt.

RECEIVED DOCUMENT
PROCESSING UNIT

1977 APR 6 PM 1 51