

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO:
MR. NORMAN C. MOSELEY

FROM:
FLORIDA POWER & LIGHT COMPANY
MIAMI, FLORIDA
A. D. SCHMIDT

DATE OF DOCUMENT
5/12/76

DATE RECEIVED
5/27/76

LETTER
 ORIGINAL
 COPY

NOTORIZED
 UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED
NONE SIGNED

DESCRIPTION

LTR. TRANS THE FOLLOWING:

(1-P)

PLANT NAME:
ST. LUCIE #1

ENCLOSURE

LICENSEE EVENT RPT. (RO 50-335/76-12) ON
4/12/76 CONCERNING MAIN STEAM ISOLATION VALVE
(MSIV HCV-08-1B) NOT MEETING TECH SPEC.

ACKNOWLEDGED
DO NOT REMOVE

(20P)

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

SAFETY

FOR ACTION/INFORMATION

ENVIRO

5/28/76

RJL

<input checked="" type="checkbox"/> BRANCH CHIEF:	ZIEMANN		
W/3 CYS FOR ACTION			
<input checked="" type="checkbox"/> LIC. ASST:	DIGGS		
W/ CYS			
ACRS 16 CYS HOLDING/SENT TO LA			

INTERNAL DISTRIBUTION

<input checked="" type="checkbox"/> REG FILE			
<input checked="" type="checkbox"/> NRC PDR			
<input checked="" type="checkbox"/> I & E (2)			
<input checked="" type="checkbox"/> MIPC (3)			
<input checked="" type="checkbox"/> SCHROEDER/IPPOLITO			
<input checked="" type="checkbox"/> HOUSTON			
<input checked="" type="checkbox"/> NOVAK/CHECK			
<input checked="" type="checkbox"/> GRIMES/SCHWENCER (1) EA			
<input checked="" type="checkbox"/> CASE			
<input checked="" type="checkbox"/> F. WILLIAMS			
<input checked="" type="checkbox"/> HANAUFER			
<input checked="" type="checkbox"/> TEDESCO/MACCARY			
<input checked="" type="checkbox"/> EISENHUT			
<input checked="" type="checkbox"/> BAER			
<input checked="" type="checkbox"/> SHAO			
<input checked="" type="checkbox"/> VOLLMER/BUNCH			
<input checked="" type="checkbox"/> KREGER/J. COLLINS			

EXTERNAL DISTRIBUTION

CONTROL NUMBER

<input checked="" type="checkbox"/> LPDR: FT. PIERCE, FL.			
<input checked="" type="checkbox"/> TIC			
<input checked="" type="checkbox"/> NSIC			

5326



May 12, 1976

PRN-LI-76-116

Mr. Norman C. Moseley, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
230 Peachtree Street, N. W., Suite 818
Atlanta, Georgia 30303



Dear Mr. Moseley:

REPORTABLE OCCURRENCE 335-76-12
ST. LUCIE UNIT 1
DATE OF OCCURRENCE: APRIL 12, 1976

MAIN STEAM ISOLATION VALVE
CLOSURE TIME

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.


Very truly yours,

A. D. Schmidt
A. D. Schmidt
Vice President
Power Resources

MAS/cpc

Attachment

Regulatory Docket File



cc: Jack R. Newman, Esquire
Director, Office of Inspection and Enforcement (30)
Director, Office of Management Information and
Program Control (3)



REPORTABLE OCCURRENCE 335-76-12
LICENSEE EVENT REPORT
PAGE TWO

EVENT DESCRIPTION (Continued)

valve stroke time. The MSIV was retested and full closure was obtained within 6 seconds of the "close" signal. This was the first occurrence of this type. (335-76-12).

CAUSE DESCRIPTION (Continued)

cushion needle valve to bypass some of the trapped air. In addition, a special test was performed to check the sizing of the air accumulator and it was found that the accumulator was undersized. A Plant Change/Modification has been performed to increase the accumulator volume for both MSIV's.

