

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION II 101 MARIETTA STREET, N.W. ATLANTA, GEORGIA 30303 Contralifele 50.280 331

OCT 2 3 1978

In Reply Refer To: RII:DJB 50-280/78-24 50-281/78-24

Virginia Electric and Power Company Attn: Mr. W. L. Proffitt Senior Vice President, Power P. O. Box 26666 Richmond, Virginia 23261

Gentlemen:

This refers to the inspection conducted by Mr. D. J. Burke of this office on September 12-15, 1978, of activities authorized by NRC Operating License Nos. DPR-32 and DPR-37 for the Surry Units 1 and 2 facilities, and to the discussion of our findings held with Mr. T. L. Baucom at the conclusion of the inspection.

Areas examined during the inspection and our findings are discussed in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspectors.

Within the scope of this inspection, no items of noncompliance were disclosed.

In accordance with Section 2.790 of the NRC's "Rules of Practice", Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room. If this report contains any information that you (or your contractor) believe to be proprietary, it is necessary that you make a written application within 20 days to this office to withhold such information from public disclosure. Any such application must include a full statement of the reasons on the basis of which it is claimed that the information is proprietary, and should be prepared so that proprietary information identified in the application is contained in a separate part of the document. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

Virginia Electric and Power Co.

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,

F. J. Long, Chief

Reactor Operations and Nuclear Support Branch

Enclosure: Inspection Report Nos.

50-280/78-24 and 50-281/78-24

cc w/encl:

Mr. T. L. Baucom, Manager

Surry Power Station

P. O. Box 315

Surry, Virginia 23883