

VIRGINIA ELECTRIC AND POWER COMPANY  
RICHMOND, VIRGINIA 23261

March 1, 1979

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Serial No. 121  
PO/DLB:scj  
Docket Nos.: 50-280  
50-281  
License Nos.: DPR-32  
DPR-37

Dear Mr. O'Reilly:

Enclosed are the Annual Operating Report, the Report of Radioactivity in Effluent Releases and Solid Wastes, and the Report of Radiological Environmental Monitoring for Surry Power Station Unit Nos. 1 and 2 as required by Surry Technical Specifications 6.6.1.b, 6.6.3.b., and 6.6.3.c., respectively. As explained in the Report of Radiological Environmental Monitoring, the operation of Surry Power Station has produced no detectable increase in offsite environmental dose rates.

The Report of Non-Radiological Environmental Monitoring required by Technical Specification 6.6.3.d. will be forwarded by March 15, 1979.

Very truly yours,

*C. M. Stallings*

C. M. Stallings  
Vice President-Power Supply  
and Production Operations

Attachments (2 copies)

cc: Mr. John G. Davis, Acting Director  
Office of Inspection and Enforcement (6 copies)

7903070375

A008  
5/3/3  
ADD:  
LTP & ENCL  
ENV SPEC BR  
RAD ASMT BR  
EPA GR SD  
R