C 03/09/18

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS) > DISTRIBUTION FOR INCOMING MATERIAL 50-335

REC: STELLO V

SUBJECT:

NRC

ORG: UHRIG R E

FL PWR & LIGHT

DOCDATE: 03/03/78

DATE RCVD: 03/07/78

DOCTYPE: LETTER

NOTARIZED: NO

COPIES RECEIVED

LTR 3 ENCL 0

FURNISHING LIST OF COMPLETED ITEMS FOR NRC"S SATISFACITON PRIOR TO CERTAIN SPECIFED TIMES AND OPERATING CONDITIONS OF LIC NO DPR-67.

PLANT NAME: ST LUCIE #1

REVIEWER INITIAL:

DISTRIBUTOR INITIAL:

******** DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS *************

GENERAL DISTRIBUTION FOR AFTER ISSUANCE OF OPERATING LICENSE. (DISTRIBUTION CODE A001)

FOR ACTION:

BR CHIEF REIDWETR-ONLY(7)

INTERNAL:

REG FILE**LTR ONLY?

I & E**LTR ONLY(2) HANAUER**LTR ONLY(1) EISENHUT ** LTR ONLY(1) BAER**LTR ONLY(1) GRIMES**LTR ONLY(1)

J. MCGOUGH**LTR ONLY(1)

NRC PDR**LTR ONLY(1) OELD**LTR ONLY(1) CHECK**LTR ONLY(1) SHAO**LTR ONLY(1) BUTLER**LTR ONLY(1) J COLLINS**LTR ONLY(1)

EXTERNAL:

LPDR'S

FT PIERCE, FL**LTR ONLY(1)

TIC**LTR ONLY(1) NSIC**LTR ONLY(1)

ACRS CAT B##LTR ONLY(16)

DISTRIBUTION:

SIZE: 2P

LTR 40

ENCL O

CONTROL NBR:

780660

THE END

n de taren de la companya de la comp Tital de la companya de la companya

The second secon



50-335

March 3, 1978 L-78-88

Office of Nuclear Reactor Regulation Attention: Mr. Victor Stello, Director Division of Operating Reactors U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Dear Mr. Stello:

Re: Completion of Conditions of License

Enclosure 1 to Operating License No. DPR-67 identified certain items which must be completed to the satisfaction of the Commission prior to certain specified times and operating conditions. This is to advise you that the following items on that list have been completed:

- I.3 Installation of redundant and independent valve position indication for the mini-flow bypass valves (V-3659 and V-3660).
- I.5 Installation of the necessary hardware associated with St. Lucie Plant Unit No. 1 to permit future interties to Unit No. 2. The systems to be so intertied are:
 - diesel generator fuel oil storage tanks
 - auxiliary feedwater system (condensate storage tank)

Additionally, item M of Enclosure 1 requires certain additional monitoring in MODE 1 if excore monitoring is used with less than 10,000MWD/MTU burnup. We wish to advise further that burnup at St. Lucie 1 exceeded 11,000 MWD/MTU as of February 13, 1978.

780660034

H001 | 5

, , e y •

Mr. Victor Stello Page Two

Accordingly, we request that items I.3, I.5, and M be deleted from Enclosure 1 to License DPR-67 as conditions of license.

Yours very truly,

pearson) Robert E. Uhrig Vice President

REU:LLL:s1

cc: Mr. J. P. O'Reilly, Region II
Harold F. Reis, Esquire
Mr. P. B. Erickson
Mr. M. V. Sinkule

. •