



ECOLOGY SERVICES, INC

9135 Guilford Road, Suite 200
Columbia, Maryland 21046
Tel (301) 362-6700
Fax (301) 490-0172

April 23, 2018

Director of FSME
Attn: GLTS
US Nuclear Regulatory Commission
Washington, DC 20555-0001

In fulfillment of the requirements of 10 CFR 31.5 (c) 8, we hereby notify you that on April 20, 2018 we transferred the self-luminous exit signs listed on the attached spreadsheet(s) to SRB Technologies, Inc, Winston-Salem, NC, license 034-0534-2. As required, for each sign listed on the spreadsheet(s), we include the name of the manufacturer, model number, and serial number. The original owner/place of installation was Dana Farber Cancer Institute, Boston, MA.

If you should have any questions, please contact Greg Keck, Ecology Services, Inc. at 301-362-6700

Sincerely,

Greg Keck
ESI Operations Manager

Encl.

DANA FARBER

17-000505

BOX ID AND INVENTORY WORKSHEET

BOX NUMBER: 1 OF 1

No.	Manufacturer	Model	Serial Number	Date of Manufacture	Original Activity (Ci)	Decayed Activity (Ci) <i>4-9-18</i>
1	ISOLITE	2000	A7N439	Nov-97	7.5	2.8
2	ISOLITE	2000	A7N441	Nov-97	7.5	2.8
3	ISOLITE	2000	A7N444	Nov-97	7.5	2.8
4	ISOLITE	2000	A7N433	Nov-97	7.5	2.8
5	ISOLITE	2000	A7N447	Nov-97	7.5	2.8
6	ISOLITE	2000	A7N442	Nov-97	7.5	2.8
7	ISOLITE	2000	A7N394	Nov-97	7.5	2.8
8	ISOLITE	2000	A7N443	Nov-97	7.5	2.8
9	OMNIGLO	700-C-12	5633	Jan-97	20.0	6.3