



NATIONAL SPINNING CO., INC.

P.O. Box 191 – 1481 W. 2nd Street
Washington, NC 27889

Donald Kennedy – Corporate Engineering

World-Class Employee-Owned Company

Director of FSME
Attn: GLTS
US Nuclear Regulatory Commission
Washington, DC 20555-001

March 20, 2018

Subject: Exit Light Disposal

To: Director of FSME; Attn: GLTS

The Beulaville National Spinning Co. Inc. facility ceased operations in December of 2017. In the facility (3) EXIT signs containing tritium were found and have been properly disposed of. The Signs were sent for disposal to SRB Technologies, Inc. (NC Radioactive Materials License Number 034-0534-2 for proper disposal. Attached is the certificate of disposal for the following items.

Exit Sign – Ever Glo Model 710-A55 serial # A-8789 Mfg. date 1-88 life rating 12 years.

Exit Sign – Ever Glo Model 710-A55 serial # A-8790 Mfg. date 1-88 life rating 12 years.

Exit Sign – Ever Glo Model 710-A55 serial # A-8794 Mfg. date 1-88 life rating 12 years.

The signs were installed in the facility;

National Spinning Co., Inc
326 Lyman Rd.
Beulaville NC 28518

Respectfully,

Donald Kennedy
Corporate Engineering
donaldek@natspin.com
910.298.1160

Attachments: Certificate of Recycling

Distribution:

Orig: Director of FSME, Attn: GLTS

1 email : Linda Fanton, CFO, National Spinning Co., Inc.

1 email : Jim Booterbaugh, President, National Spinning Co., Inc.

Tracking Number
411830474451

LAMPMASTER

Certificate of Recycling

This document certifies that the following item:

Tritium Exit Sign Disposal (4lbs)

Was received on Mar 05, 2018 for recycling by

Lampmaster Recycling Services, LLC from:

National Spinning Co - Donald Kennedy

326 Lyman Rd

Beulaville, NC 28518

USA Lamp & Ballast Recycling, Inc. / Cleanlites Recycling certifies that all waste materials accepted are recycled or (if not recyclable) disposed of in accordance with all applicable Federal, State, and Local regulations and within all regulated time periods.

Lampmaster Recycling Services, LLC
419 Northland Blvd
Cincinnati, Ohio 45240

By: 
WWW.Lampmaster.com