

EBASCO SERVICES

INCORPORATED

ENGINEERS - CONSTRUCTORS - CONSULTANTS

ONE JERICHO PLAZA

JERICHO, N. Y. 11753

CABLE ADDRESS "EBASCOE"

June 12, 1980
NRC-1

Mr Harold R Denton, Director
Office of Nuclear Reactor Regulation
US Nuclear Regulatory Commission
Washington, DC 20555

Dear Mr Denton:

Subject: SHOW CAUSE ORDER REANALYSIS REPORT
REVISION NO. 1
SURRY POWER STATION UNIT 2

References: Serial No.: 138B
Docket No.: 50-281
License No.: DPR-37

Ebasco Services, Inc is resubmitting forty-five (45) copies of Revision 1 of the "Report on the Reanalysis of Safety-Related Piping Systems, Surry Power Station Unit 2, Virginia Electric and Power Company," originally hand delivered April 11, 1980.

Please replace the forty-five (45) copies submitted on April 11, 1980 (white cover) with those enclosed (beige cover).

The resubmittal is for two (2) reasons:

- 1) General illegibility of Appendix B flow diagrams
- 2) Errata on Appendix B, Page B-2

Main Steam Drawing No. 11548-FM-14A

Feedwater Drawing No. 11548-FM-18A

are Revision 1 but were not indicated as such.

*Acc 1
5/45
XTRAS TO
BC*

8006180249

P

Mr Harold R Denton

-2-

June 12, 1980

We apologize for any inconvenience this may have caused.

Very truly yours,



H W Nelson
Project Manager

HWN/JNR/bfl
Enclosures

cc: Mr Victor Stello, Director
Office of Inspection and Enforcement

Mr James P O'Reilly, Director
Office of Inspection and Enforcement, Region II

bc: Mr. J. H. Ferguson Mr. G. A. Helm Mr. D. F. Cochran
Mr. Sam C. Brown, Jr. Mr. A. L. Parrish, III Mr. G. L. Strickler
Mr. W. C. Spencer Mr. R. H. Woodall, III Mr. M. W. Maupin
Mr. C. M. Stallings Mr. F. M. Alligood, Jr. Mr. H. W. Nelson - Ebasco
Mr. E. A. Baum Mr. R. M. Berryman Mr. J. M. Daly
Mr. J. W. Waddill Mr. C. M. Robinson, Jr. Mr. R. K. MacManus
Mr. D. W. Speidell, Jr. Mr. W. T. Davidson - Surry Mr. J. L. Perkins
Mr. W. C. Daley Mr. J. L. Wilson - Surry Mr. T. A. Peebles - Surry
Mr. B. R. Sylvia Mr. B. R. Crowe - S&W Mr. S. C. Rossier - S&W
Mr. J. C. Harris, Jr.