REGULATORY DUCKET FILE COPY

Docket Nos. 50-280 and 50-281

> Mr. J. H. Ferguson Executive Vice President - Power Virginia Electric and Power Company Post Office Box 26666 Richmond, Virginia 23261

Dear Mr. Ferguson:

We have reviewed your response to our November 9, 1979 letter concerning those portions of your ECCS evaluation models, dealing with fuel cladding swelling and incidence of rupture.

We find that you have adequately confirmed the representations made in your behalf by your fuel supplier. We, therefore, conclude that your response is acceptable and that no further action is necessary at this time.

Sincerely,

Original signed by 8 S. A. Varga

Steven A. Varga, Chief Operating Reactors Branch #1 Division of Licensing

cc: See next page

8010010172

OFFICE DE CORPONING DE CORPONIN



UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

SEPTEMBER 1 2 1980

Docket Nos. 50-280 and 50-281

Mr. J. H. Ferguson Executive Vice President - Power Virginia Electric and Power Company Post Office Box 26666 Richmond, Virginia 23261

Dear Mr. Ferguson:

We have reviewed your response to our November 9, 1979 letter concerning those portions of your ECCS evaluation models, dealing with fuel cladding swelling and incidence of rupture.

We find that you have adequately confirmed the representations made in your behalf by your fuel supplier. We, therefore, conclude that your response is acceptable and that no further action is necessary at this time.

Sincerely,

Steven A. (Varga, Chief Operating Reactors Branch #1 Division of Licensing

cc: See next page

cc: Mr. Michael W. Maupin Hunton and Williams Post Office Box 1535 Richmond, Virginia 23213

> Mr. J. L. Wilson, Manager P. O. Box 315 Surry, Virginia 23883

Swem Library College of William and Mary Williamsburg, Virginia 23185

Donald J. Burke, Resident Inspector Surry Power Station U. S. Nuclear Regulatory Commission Post Office Box 959 Williamsburg, Virginia 23185