

ATTACHMENT 1
SURRY POWER STATION, UNIT
DOCKET NO: 50-280
REPORT NO: 80-044/03L-0
EVENT DATE: 07-07-80

TITLE OF EVENT: TRANSFER PUMP BREAKER INADVERTANTLY OPENED

1. Description of Event:

While performing Periodic Test 22.2, which is designed to prove the operability of the diesel fuel oil transfer pumps, it was found that the circuit breaker for 1-EE-P-1F was open. This is contrary to Technical Specification 3.16.A55 and is Reportable as per Technical Specification 6.6.2.b. (2).

2. Probable Consequences and Status of Redundant Systems:

The alternate flow path through 1-EE-P-1C was operable and capable of supplying fuel oil to #3 emergency diesel day tank. The health and safety of the public were not affected.

3. Cause:

The breaker was inadvertently opened by personnel working in the vicinity of the motor control center.

4. Immediate Corrective Action:

Reclosed the circuit breaker and tested the pump as per Periodic Test 22.2.

5. Subsequent Corrective Action:

None Required

6. Action Taken to Prevent Recurrence:

None Required

7. Generic Implications

None