Centraldile



UNITED STATES NUCLEAR REGULATORY COMMISSION REGION II

101 MARIETTA ST., N.W., SUITE 3100 ATLANTA, GEORGIA 30303

FEB 1 1 1981

Virginia Electric and Power Company ATTN: J. H. Ferguson Executive Vice President-Power P. O. Box 26666 Richmond, VA 23261

Gentlemen:

Subject: Report Nos. 50-280/80-44 and 50-281/80-48

This refers to the routine safety inspection conducted by D. J. Burke of this office on December 1-24, 1980, of activities authorized by NRC Operating License DPR-32 and DPR-37 for the Surry facility, and to the discussion of our findings held with J. L. Wilson at the conclusion of the inspection.

Areas examined during the inspection and our findings are discussed in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, no violations or deviations were disclosed.

We have examined actions you have taken with regard to previously identified enforcement matters. These are discussed in the enclosed inspection report.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room. If this report contains any information that you (or your contractor) believe to be proprietary, it is necessary that you make a written application within 20 days to this office to withhold such information from public disclosure. Any such application must include a full statement of the reasons on the basis of which it is claimed that the information is proprietary, and should be prepared so that proprietary information identified in the application is contained in a separate part of the document. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

Should you have any questions concerning this letter, we will be glad to discuss them with you.

SERVICES UNITURN SERVICES UNITURN SERVICES UNITURN SERVICES ON 3 24

See STREEUTION SERVICES


See Franch Control of the Contro

Sincerely,

R. C. Tewis, Acting Chief

Reactor Operations and Nuclear

Support Branch



Enclosure: Inspection Report Nos. 50-280/80-44 and 50-281/80-48

cc w/encl: J. L. Wilson, Manager