

Vepco

VIRGINIA ELECTRIC AND POWER COMPANY

March 19, 1981

Mr. N. M. Haller, Director
Office of Management and
Program Analysis
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Serial No. 185
NO/RET:ycf
Docket Nos. 50-280
50-281
License Nos. DPR-32
DPR-37

Dear Mr. Haller:

We have recently discovered an error in our Monthly Operating Reports for our Surry Units 1 and 2. The error is in line 5, Design Electrical Rating (Net MWe). We have been reporting this figure as 822, this is our gross design electrical rating. The correct figure should be 788. The correct figure will appear commencing with our March, 1981 report. Please make the necessary corrections to your NUREG-0020, "Licensed Operating Reactors - Status Summary Report" and accept my apologies for this error.

Sincerely,



B. R. Sylvia
Manager - Nuclear
Operations and Maintenance

cc: Mr. Victor Stello, Director
Office of Inspection and Enforcement

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement - Region II



A008
s
1/0

8103260379

P