

U. S. NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT
REGION II

FEB 13 1981

Report Nos. 50-280/81-03 and 50-281/81-03

Docket Nos. 50-280 and 50-281

License Nos. DPR-32 and DPR-37

Licensee: Virginia Electric and Power Company
P. O. Box 26666
Richmond, VA 23261

Facility Name: Surry 1 and 2

Inspection at Surry, Virginia

Inspection conducted: January 12-16, 1981

Date of Last Physical Security Inspection Visit: September 28 - October 2,
1980

Type of Inspection: Unannounced Physical Security

Inspectors:

C. D. Perny (for)
C. D. Perny, Physical Security Inspector

2/13/81
Date Signed

A. O. Hill
A. O. Hill, Physical Security Inspector

2/13/81
Date Signed

Approved by:

D. McGuire
D. McGuire, Section Chief, Safeguards Branch

2/13/81
Date Signed

Inspection Summary

Areas Inspected: Included review of the security plan, security program audit, security organization, lighting, alarm stations, assessment aids, records and reports and licensee action on previous inspection findings.

The inspection involved 78 inspector hours on site by two NRC inspectors. The inspection was begun during an offshift period; 21 inspection hours were accomplished during offshift periods.

Results: The licensee was found to be in compliance with NRC requirements within the eight areas examined during the inspection except for the following two areas:

1. Physical Barriers (Vital/Protected Area) - Certification of the bullet resistance of the control room, central alarm station and other security related structures (Unresolved).

S-F2 81 - 22
Copy 8 of 22 Pages
Copies

This Document is not to be
reproduced without specific
approval of IE:II

8104060093

2. Alarm Stations - Failure to follow commitments in the Security Plan for operation of the security alarm stations (Violation).