

VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

April 5, 1988

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D. C. 20555

Serial No. 88-069
NOD/SBE:vlh
Docket Nos. 50-280
50-281
License Nos. DPR-32
DPR-37


Gentlemen:

VIRGINIA ELECTRIC AND POWER COMPANY
SURRY POWER STATION UNITS 1 AND 2
RESPONSE TO NRC BULLETIN 88-01
(TACS 65955/65956)

As requested by the NRC Bulletin 88-01 "Defects in Westinghouse Circuit Breakers," a review of the circuit breakers installed in Surry Units 1 and 2 was conducted. It was determined that there are no Westinghouse Type DS breakers used at Surry Power Station.

The information provided in this response is true and accurate to the best of my knowledge. If additional information is required, please let me know.

Very truly yours,



D. S. Cruden
Vice President - Nuclear

cc: U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, N. W.
Suite 2900
Atlanta, Georgia 30323

Mr. W. E. Holland
NRC Senior Resident Inspector
Surry Power Station

8804120234 880405
PDR ADOCK 05000280
PDR

JEH
1/1

