

**Virginia Electric And Power Company  
Surry Power Station  
5570 Hog Island Road  
Surry, Virginia 23883**

December 4, 1998

U. S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, D. C. 20555

Serial No.: 98-710  
SPS: BAG  
Docket No.: 50-280  
50-281  
License No.: DPR-32  
DPR-37


Dear Sirs:

Pursuant to 10 CFR 73.71(d), Virginia Electric and Power Company hereby submits the following Licensee Event Report applicable to Surry Power Station Units 1 and 2.

Report No. 50-280, 50-281/1998-S01-00

This report has been reviewed by the Station Nuclear Safety and Operating Committee and will be forwarded to the Management Safety Review Committee for its review.

Very truly yours,



E. S. Grecheck  
Site Vice President

Enclosure

Commitments contained in this letter:

1. A root cause evaluation (RCE) has been initiated. Recommendations from the RCE, deemed necessary to prevent recurrence, will be implemented when the evaluation is complete.

9812100004 981204  
PDR ADOCK 05000280  
S PDR

//  
I 74

cc: U. S. Nuclear Regulatory Commission  
Region II  
Atlanta Federal Center  
61 Forsyth Street, SW, Suite 23T85  
Atlanta, Georgia 30303

Mr. R. A. Musser  
NRC Senior Resident Inspector  
Surry Power Station