

**Virginia Electric And Power Company
Surry Power Station
5570 Hog Island Road
Surry, Virginia 23883**

December 4, 1998

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D. C. 20555

Serial No.: 98-710
SPS: BAG
Docket No.: 50-280
50-281
License No.: DPR-32
DPR-37


Dear Sirs:

Pursuant to 10 CFR 73.71(d), Virginia Electric and Power Company hereby submits the following Licensee Event Report applicable to Surry Power Station Units 1 and 2.

Report No. 50-280, 50-281/1998-S01-00

This report has been reviewed by the Station Nuclear Safety and Operating Committee and will be forwarded to the Management Safety Review Committee for its review.

Very truly yours,



E. S. Grecheck
Site Vice President

Enclosure

Commitments contained in this letter:

1. A root cause evaluation (RCE) has been initiated. Recommendations from the RCE, deemed necessary to prevent recurrence, will be implemented when the evaluation is complete.

9812100004 981204
PDR ADOCK 05000280
S PDR

11
I 74

cc: U. S. Nuclear Regulatory Commission
Region II
Atlanta Federal Center
61 Forsyth Street, SW, Suite 23T85
Atlanta, Georgia 30303

Mr. R. A. Musser
NRC Senior Resident Inspector
Surry Power Station