

VIRGINIA ELECTRIC AND POWER COMPANY  
RICHMOND, VIRGINIA 23261

August 24, 1992

United States Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, D. C. 20555

Serial No. 92-501  
NL&P/CGL R0  
Docket Nos. 50-280  
50-281  
License Nos. DPR-32  
DPR-37

Gentlemen:

**VIRGINIA ELECTRIC AND POWER COMPANY**  
**SURRY POWER STATION UNITS 1 AND 2**  
**INDIVIDUAL PLANT EXAMINATION -**  
**REQUEST FOR ADDITIONAL INFORMATION ON**  
**RESOLUTION OF GENERIC ISSUE GI-23**

In a letter dated July 17, 1992, the NRC requested additional information on the Surry Individual Plant Examination (IPE) regarding resolution of Generic Issue GI-23, "Reactor Coolant Pump Seal Failures." In a telephone conversation between Mr. B. C. Buckley, the NRC Project Manager, and a member of my staff, we requested and were granted additional time to prepare our response to this request. The additional preparation time was requested to ensure that Station Blackout, Inservice Inspection, and other issues related to reactor coolant pump seals are more thoroughly addressed. A secondary reason for requesting the additional time is that the same personnel preparing this response are also actively involved in meeting the schedule for preparation of the North Anna IPE report.

As agreed to in the August 18, 1992 conversation, we will provide the response to your request for additional information by September 24, 1992.

Very truly yours,



W. L. Stewart  
Senior Vice President - Nuclear

9209010120 920824  
PDR ADDCK 05000280  
PDR

A001  
110

cc: U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, N. W.  
Suite 2900  
Atlanta, Georgia 30323

Mr. M. W. Branch  
NRC Senior Resident Inspector  
Surry Power Station