

NOT TO SCALE

NOTE: SEE TABLE 12.2-1 FOR IDENTIFICATION OF NUMBERED LOCATIONS.

FIGURE 12.2-1

**RADIATION SOURCE MODEL** 

FIGURE 12.3-1

RADIATION ZONES — PLANT PLAN VIEW EL. 65'-0" TO 67'-6"

FIGURE 12.3-2

RADIATION ZONES — PLANT PLAN VIEW EL. 95'-0" TO 126'-0"

FIGURE 12.3-3

RADIATION ZONES - PLANT PLAN VIEW EL.123'-6" TO 148'-0"

RIVER BEND STATION UPDATED SAFETY ANALYSIS REPORT

REVISION 16 MARCH 2003

#### FIGURE 12.3-4

RADIATION ZONES — PLANT PLAN VIEW EL. 113' & 114'; 162'-3" & 170'; 166'; 186'-3"

FIGURE 12.3-5A

RADIATION ZONES — PLAN VIEW OF SERVICES BUILDING EL. 123'-6"

**FIGURE 12.3-5B** 

RADIATION ZONES — PLAN VIEW OF SERVICES BUILDING EL 109'-3"

FIGURE 12.3-6

SHIELDING ARRANGEMENT AND FACILITIES
EL. 65'-0" TO 67'-6"

RIVER BEND STATION

UPDATED SAFETY ANALYSIS REPORT

REVISION 15

MAY 200




FIGURE 12.3-7

SHIELDING ARRANGEMENT AND FACILITIES - EL 95'-0" TO 126'-0"

RIVER BEND STATION

UPDATED SAFETY ANALYSIS REPORT

REVISION 15 MAY 2002

SHIELDING ARRANGEMENT AND FACILITIES-EL.123'-6" TO 148'-0"

FIGURE 12.3-9

SHIELDING ARRANGEMENT AND FACILITIES-EL. 113' & 114'; 162'-3" & 170'; 186'-3"


RIVER BEND STATION


UPDATED SAFETY ANALYSIS REPORT


REVISION 15


MAY 20

(THIS FIGURE HAS BEEN DELETED)	
	EICLIDE: 12.2.10A
	FIGURE 12.3-10A  RADIATION ZONES — PLAN VIEW OF SERVICES BUILDING EL. 123'-6"
	RIVER BEND STATION UPDATED SAFETY ANALYSIS REPORT











PLAN

FIGURE 12.3-11

FUEL TRANSFER TUBE AREA RADIATION BARRIERS





#### FIGURE 12.3-13

FUEL BUILDING CHARCOAL FILTRATION SYSTEM




FIGURE 12.3-15, SHEET 1

POST-LOCA VITAL AREA ACCESS-ROUTES TO AND FROM MAIN PLANT EXHAUST DUCT MONITOR GRAB SAMPLE AREA

FIGURE 12.3-15, SHEET 2

POST-LOCA VITAL AREA ACCESS—ROUTES
TO AND FROM MAIN PLANT EXHAUST
DUCT MONITOR GRAB SAMPLE AREA

RIVER BEND STATION

FIGURE 12.3-15, SHEET 3

POST-LOCA VITAL AREA ACCESS—ROUTES TO AND FROM MAIN PLANT EXHAUST DUCT MONITOR GRAB SAMPLE AREA

RIVER BEND STATION

UPDATED SAFETY ANALYSIS REPORT REV 6 AUGUST 1993

**FIGURE 12.3-15, SHEET 4** 

POST-LOCA VITAL AREA ACCESS—ROUTES TO AND FROM MAIN PLANT EXHAUST DUCT MONITOR GRAB SAMPLE AREA

RIVER BEND STATION

FIGURE 12.3-15, SHEET 5

POST-LOCA VITAL AREA ACCESS—ROUTES
TO AND FROM MAIN PLANT EXHAUST
DUCT MONITOR GRAB SAMPLE AREA

**FIGURE 12.3-15, SHEET 6** 

POST-LOCA VITAL AREA ACCESS — ROUTES TO AND FROM MAIN PLANT EXHAUST DUCT MONITOR GRAB SAMPLE AREA

RIVER BEND STATION

FIGURE 12.3-15, SHEET 7

POST-LOCA VITAL AREA ACCESS—ROUTES TO AND FROM MAIN PLANT EXHAUST DUCT MONITOR GRAB SAMPLE AREA

RIVER BEND STATION

FIGURE 12.3-16, SHEET 1

POST-LOCA VITAL AREA ACCESS —
ROUTES TO AND FROM POST-ACCIDENT
SAMPLE PANEL

RIVER BEND STATION

FIGURE 12.3-16, SHEET 2


POST-LOCA VITAL AREA ACCESS—ROUTES TO AND FROM POST-ACCIDENT SAMPLE PANEL

RIVER BEND STATION

FIGURE 12.3-16, SHEET 3

POST-LOCA VITAL AREA ACCESS —
ROUTES TO AND FROM POST-ACCIDENT
SAMPLE PANEL

RIVER BEND STATION



POST-ACCIDENT SAMPLE ROOM

RIVER BEND STATION FINAL SAFETY ANALYSIS REPORT