NRC FORM 591M PART 1 (07-2012)* 10 CFR 2.201		Ü	U.S. NUCLEAR REGULATORY COMMISSION		
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION					
LICENSEE/LOCATION INSPECTED: Valley Inspection Service, Inc. 430 Business Park Lane Allentown, PA 18109 REPORT NUMBER(S) 2018-001		NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713			
3. DOCKET NUMBER(S)	4. LICENSE NUMBE	R(S)	5. DATE(S) OF INSPECT	ION	
030-31172	37-28385-01		July 11-12, 2018		
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X					
I hereby state that, within 30 days, the corrective actions is made in accordar date when full compliance will be achi	nce with the requirements of 10 C	FR 2.201 (corrective steps alre	ady taken, corrective steps v	which will be taken,	
Title	Printed Name	whiten response to NIC will t	Signature	Date	
LICENSEE'S REPRESENTATIVE					
NRC INSPECTOR	Michael Reichard	Mill	1 Re. Wo	7/12/18	
BRANCH CHIEF	Arthur Burritt	ad	12/12	7/13/18	
*NRC FORM 591M PART 1 (07-2012) (RI Rev. 09/12/2013)	G:\WordDocs\Current\Insp Rec	ord\R37-28385-01.2018-00	1.591M-Part1.doc	

SUNSI Review Completed By: /RA / Michael Reichard X Public X Non-Sensitive