



Washington Public Power Supply System
A JOINT OPERATING AGENCY

P. O. Box 988

3000 GEO. WASHINGTON WAY

RICHLAND, WASHINGTON 99352

PHONE (509) 375-5000

March 3, 1978
602-78-84

Nuclear Regulatory Commission
Region V
Suite 202, Walnut Creek Plaza
1990 N. California Boulevard
Walnut Creek, CA 94596

Attention: Mr. R. H. Engelken
Director

Subject: WPPSS NUCLEAR PROJECT NO. 2
IE BULLETIN NO. 78-02
DOCKET NO. 50-397

Reference: Letter, R. H. Engelken to N. O. Strand, Same Subject,
January 30, 1978.

Dear Mr. Engelken:

The reference letter transmitted the subject IE Bulletin. In response to the questions asked in IE Bulletin No. 78-02, our AE reports that there are no unprotected terminal blocks used in WNP-2 in systems which must function in the post-accident environment.

The above information supports our compliance with IE Bulletin 78-02.

Very truly yours,

D. L. RENBERGER
Assistant Director
Generation & Technology

DLR:GLC:ct

cc: Mr. D. Roe, Bonneville Power Administration
NRC, Office of Inspection and Enforcement (Washington D.C.)



AO 7
GD