

CENTRAL  
MAIL

AMERICAN ELECTRIC POWER Service Corporation



2 Broadway, New York, N. Y. 10004  
(212) 422-4800

JOHN E. DOLAN  
Senior Executive Vice President  
Engineering

August 16, 1978  
AEP:NRC: 00045

Donald C. Cook Nuclear Plant Units 1 & 2  
Docket Nos. 50-315 and 50-316  
License Nos. DPR-58 and DPR-74

Mr. J. G. Keppler, Regional Director  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Dear Mr. Keppler:

This letter responds to your letter of June 27, 1978 which transmitted to us IE Bulletin No. 78-10 entitled "Bergen-Paterson Hydraulic Shock Suppressor Accumulator Spring Coils."

Our review indicated that the Donald C. Cook Nuclear Plant has no Bergen-Paterson snubbers installed in safety-related systems, nor are there any in our spare parts inventory.

Very truly yours,

A handwritten signature in cursive script that reads "John E. Dolan".  
John E. Dolan

JED:em

cc: R. C. Callen  
G. Charnoff  
P. W. Steketee  
R. J. Vollen  
R. Walsh  
D. V. Shaller - Bridgman  
R. W. Jurgensen  
H. D. Thornberg

AUG 21 1978

AO 2  
GD

