

05/24/78

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)
DISTRIBUTION FOR INCOMING MATERIAL

50-316

REC: KEPPLER J G
NRC

ORG: SHALLER D V
IN & MI PWR

DOCDATE: 05/16/78
DATE RCVD: 05/22/78

DOCTYPE: LETTER NOTARIZED: NO
SUBJECT:

COPIES RECEIVED
LTR 1 ENCL 1

FORWARDING LICENSEE EVENT REPT (RO 50-316/78-027) ON 04/22/78 CONCERNING
DURING OHP. 4030. STP. 020, CMO 414 FAILED TO OPERATE IN ITS PRESCRIBED TIME,
CONSTITUTING AN INOPERABLE AUTOMATIC VALVE REQUIRED BY TECH SPEC 4.7.3.1.

PLANT NAME: COOK - UNIT 2

REVIEWER INITIAL: XJM
DISTRIBUTOR INITIAL: ML

***** DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS *****

NOTES:

1. SEND 3 COPIES OF ALL MATERIAL TO I&E

INCIDENT REPORTS
(DISTRIBUTION CODE A002)

FOR ACTION: ~~BR-CHIEF-KNIEL**W/4 ENCL~~

INTERNAL:

REG FILE**W/ENCL
~~I & E**W/2 ENCL~~
IPPOLITO**W/ENCL
NOVAK/CHECK**W/ENCL
KNIGHT**W/ENCL
HANAUER**W/ENCL
EISENHUT**W/ENCL
SHAO**W/ENCL
KREGER/J. COLLINS**W/ENCL
K SEYFRIT/IE**W/ENCL

NRC PDR**W/ENCL
MIPC**W/3 ENCL
HOUSTON**W/ENCL
EEB**W/ENCL
BUTLER**W/ENCL
TEDESCO**W/ENCL
BAER**W/ENCL
VOLLMER/BUNCH**W/ENCL
ROSA**W/ENCL

EXTERNAL:

LPDR'S
ST. JOSEPH, MI**W/ENCL
TIC**W/ENCL
NSIC**W/ENCL
ACRS CAT B**W/16 ENCL


COPIES NOT SUBMITTED PER
REGULATORY GUIDE 10.1

DISTRIBUTION: LTR 45 ENCL 45
SIZE: 1P+1P

CONTROL NBR: 781440045

THE END

60





INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106

May 16, 1978

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-74
Docket No. 50-316

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications
the following report is submitted:

RO 78-027/03L-0.

Sincerely,

D.V. Shaller
Plant Manager

/bab

cc: J.E. Dolan
R.W. Jurgensen
R.F. Kroeger
R. Kilburn
R.J. Vollen BPI
K.R. Baker RO:III
R.C. Callen MPSC
P.W. Steketee, Esq.
G. Charnoff, Esq.
R. Walsh, Esq.
G. Olson
J.M. Hennigan
PNSRC
J.F. Stietzel
Dir., IE (30 copies)
Dir., MIPC (3 copies)

MAY 18 1978

As of
60

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	D	C	C	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5	
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE				30	57	CAT		58

CON'T

REPORT SOURCE L 6 0 5 0 0 0 3 1 6 7 0 4 2 2 7 8 8 0 5 1 6 7 8 9

DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | DURING OHP. 4030.STP.020, CMO 414 FAILED TO OPERATE IN ITS PRESCRIBED TI

ME. THIS CONSTITUTED AN INOPERABLE AUTOMATIC VALVE REQUIRED BY TECHNICAL

0 4 L SPECIFICATION 4.7.3.1. CMO 414 WAS SUCCESSFULLY STROKED MANUALLY, AND

05 | THEREFORE COULD HAVE BEEN REPOSITIONED IN THE EVENT OF AN EMERGENCY. TH

06 E VALVE MOTOR OPERATOR WAS TAGGED OUT FOR REPAIRS.

07 _____

[illegible]

7 8

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

0 9 11 12 13 14 15 16

W B E A V A L V O P A Z

9 10 11 12 13 14 15 16 17 18 19 20

(17) LER/RO REPORT NUMBER

EVENT YEAR		REPORT NO.			CODE	TYPE	NO.
7	8	0	2	7	03	L	0
21	22	23	24	26	27	28	29

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS				ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER		
E	18	Z	19	Z	20	Z	21	0	0	0	0	N	23	Y	24	A	25	L	2	0
33		34		35		36		37			40	41		42		43		44		

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 INVESTIGATION REVEALED THAT CMO 414 LIMITORQUE L56 MOTOR OPERATOR'S TORQ

1 1 UE AND AUXILIARY SWITCHES HAD CONTACTS THAT REQUIRED BURNISHING AND WERE

1 2 OUT OF ADJUSTMENT. THIS CONDITION WAS DUE TO NORMAL CONTACT WEAR. THE

1	3	CONTACTS WERE CLEANED AND ADJUSTED. OPERATIONAL CHECKS FOLLOWING REPAIR
---	---	---

1 4 S WERE SATISFACTORY. NO FURTHER ACTIONS ARE PLANNED.

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FACILITY STATUS (28) G % POWER (29) 0 0 0 OTHER STATUS (30) NA METHOD OF DISCOVERY (31) B DISCOVERY DESCRIPTION (32) SURVEILLANCE TESTING

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 7 8 9 10 11

33 34

AMOUNT OF ACTIVITY NA

35

44

45

LOCATION OF RELEASE NA

36

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION	(39)				
1	7	0	0	0	(37)	Z	(38)	NA	

7	8	9	11	12	13
PERSONNEL INJURIES					
NUMBER		DESCRIPTION (41)			
		NA			

1 8 0 0 0 (40) NA
7 8 9 11 12
LOSS OF OR DAMAGE TO FACILITY (43)

TYPE		DESCRIPTION	NA
1	9	Z	(42)

ISSUED (44) NA DESCRIPTION (45) PUBLICITY NRC USE ONLY

NAME OF PREPARER M. S. Brown

PHONE: 616-465-5901