

**NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)**

CONTROL NO: 12034

FILE: INCIDENT REPORT FILE

FROM: Indiana & Michigan Power Co Bridgman, Michigan R.W. Jurgensen		DATE OF DOC 10-10-75	DATE REC'D 10-16-75	LTR XXX	TWX	RPT	OTHER
TO: Mr. J.G. Keppler		ORIG None	CC 30	OTHER	SENT AEC PDR SENT LOCAL PDR		XXX XXX
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 30	DOCKET NO: 50-315		

DESCRIPTION:
Letter requesting removal of A/O 50-315/75-21 from the records for the Donald C. Cook Nuclear Plant.
(30 Copies Enclosure Received)

ENCLOSURES:

PLANT NAME: Donald C. Cook#1

FOR ACTION/INFORMATION

SAB 10-17-75

- | | | | |
|-------------------------|----------------------------|-----------------------------|------------------------|
| BUTLER (L)
W/ Copies | SCHWENCER (L)
W/ Copies | ZIEMANN (L)
W/ Copies | REGAN (E)
W/ Copies |
| CLARK (L)
W/ Copies | STOLZ (L)
W/ Copies | DICKER (E)
W/ Copies | LEAR (L)
W/ Copies |
| PARR (L)
W/ Copies | VASSALLO (L)
W/ Copies | KNIGHTON (E)
W/ Copies | SPELS
W/ Copies |
| KNIEL (L)
W/ Copies | PURPLE (L)
W/ Copies | YOUNGBLOOD (E)
W/ Copies | W/ Copies |

**DO NOT REMOVE
ACKNOWLEDGED**

INTERNAL DISTRIBUTION

- | | | | | |
|---|---|---|--|--|
| <u>REG FILE</u>
- NRC PDR
- OGC, ROOM P-506A
GOSSICK/STAFF
- CASE
GIAMBUSSO
BOYD
MOORE (L)
DEYOUNG (L)
SKOVHOLT (L)
GOLLER (L) (Ltr)
P. COLLINS
DENISE
REG OPR
- FILE & REGION (2)
- MIPC/PE (3)
STEELE | <u>TECH REVIEW</u>
- SCHROEDER
- MACCARY
KNIGHT
PAWLICKI
SHAO
** STELLO
** HOUSTON
** NOVAK
- ROSS
- IPPOLITO
- TEDESCO
J. COLLINS
LAINAS
BENAROYA
- VOLLMER | DENTON
** GRIMES
GAMMILL
KASTNER
BALLARD
SPANGLER

<u>ENVIRO</u>
MULLER
DICKER
KNIGHTON
YOUNGBLOOD
REGAN
PROJECT LDR


<u>HARLESS</u> | <u>LIC ASST</u>
R. DIGGS (L)
H. GEARIN (L)
E. GOULBOURNE (L)
P. KREUTZER (E)
J. LEE (L)
M. MAIGRET (L)
S. REED (E)
- M. SERVICE (L)
S. SHEPPARD (L)
M. SLATER (E)
H. SMITH (L)
S. TEETS (L)
G. WILLIAMS (E)
V. WILSON (L)
R. INGRAM (L) | <u>A/T IND.</u>
BRAITMAN
SALTZMAN
MELTZ

<u>PLANS</u>
MCDONALD
CHAPMAN
DUBE (Ltr)
E. COUPE
PETERSON
HARTFIELD (2)
- KLECKER
EISENHUT
- WIGGINTON

- F. WILLIAMS
- HANAUER |
|---|---|---|--|--|

EXTERNAL DISTRIBUTION

- | | | |
|------------------------------------|--------------------------------|---|
| 1 - LOCAL PDR St. Joseph, Michigan | 1 - NATIONAL LABS | 1 - PDR-SAN/LA/NY |
| 1 - TIC (ABERNATHY) (1)(2)(10) | 1 - W. PENNINGTON, Rm E-201 GT | 1 - BROOKHAVEN NAT LAB |
| 1 - NSIC (BUCHANAN) | 1 - CONSULTANTS | 1 - G. ULRIKSON, ORNL |
| 1 - ASLB | NEWMARK/BLUME/AGBABIAN | 1 - AGMED (RUTH GUSSMAN)
Rm B-127 GT |
| 1 - Newton Anderson | M. Service | 1 - J. D. RUNKLES, Rm E-201
GT |
| 5 - ACRS SENT TO LIC ASST | | |
| ** SEND ONLY TEN DAY REPORTS | | |





INDIANA & MICHIGAN POWER COMPANY



DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106

Regulatory

File Cy.

October 10, 1975

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137



Operating License DPR-58
Docket No. 50-315

Dear Mr. Keppler:

We have reviewed the requirements of Appendix A Technical Specifications Sections 3.1.2.2 and 4.1.2.2 and are of the opinion that the event reported on June 30, 1975, in Abnormal Occurrence Report AO 50-315/75-21 for the Donald C. Cook Nuclear Plant, was incorrectly reported as an Abnormal Occurrence.

The emergency boration valve (QMO-410) was operational to the 3/4 open position which permits full flow for this valve design. A flow test verified that the minimum flow requirement of 70 gpm could be met with the valve in the 3/4 open position. The valve indicator correctly indicated the 3/4 open position. The incident was reported because the valve itself was not fully open even though the boration flow rate met the requirements. However, Appendix A Technical Specification 4.1.2.2(b) only requires exercising all testable remotely operated valves in the flow path. This requirement was satisfied by opening the valves to the 3/4 open position.

We, therefore, request the Nuclear Regulatory Commission to remove Abnormal Occurrence Report No. AO 50-315/75-21 from the records for the Donald C. Cook Nuclear Plant.

Sincerely,

R.W. Jurgensen
Plant Manager

/bab

cc: R.S. Hunter
J.E. Dolan
G.E. Lien.

12034

R. Kilburn
R.J. Vollen BPI
R.C. Callen MPSC
K.R. Baker RO: III
P.W. Steketee, Esq.
R. Walsh, Esq.
G. Charnoff, Esq.
G. Olson
PNSRC
R.S. Keith
Director, IE (30 copies)
Director, MIPC (3 copies)

