



August 7, 2018

U.S. Nuclear Regulatory Commission
Nuclear Material Safety and Safeguards
Division of Decommissioning, Uranium Recovery, and Waste Programs
Uranium Recovery Licensing Branch
Attention: Mr. Ronald Burrows, Project Manager
Two White Flint North, Mail Stop T8 F5
11545 Rockville Pike
Rockville, MD 20852

Re: Strata Energy Ross In Situ Recovery Project
Source Materials License SUA-1601, Docket No. 040-09091
Additional Clarifications Regarding License Condition 12.7

Dear Mr. Burrows:

In response to requests from NRC staff for clarification of commitments that Strata Energy, Inc. (Strata) has made to address License Condition 12.7, Strata is providing the following regarding external exposure monitoring methods at the Ross project. By letter dated July 30, 2015 (ADAMS Accession No. ML15224B400), Strata stated in response to Comment 9 that dosimeters would be worn by all regular full time employees to monitor external radiation per the Technical Report (TR) Section 5.7.2.3. This statement was inconsistent with a response Strata submitted to NRC staff regarding License Condition 12.9 (ADAMS Accession No. ML15219A188), which allows Strata to make changes to the external exposure monitoring program under certain conditions. The response to Comment 9 for License Condition 12.7 should have referenced the License Condition 12.9 submittal rather than TR Section 5.7.2.3.

Please contact me if you have any questions. You can reach me at (307) 467-5995 or mgriffin@stratawyo.com.

Sincerely,

Strata Energy, Inc.

A handwritten signature in blue ink, appearing to read "M. Griffin", is written over the printed name.

Michael Griffin

Vice President of Permitting, Regulatory and Environmental Compliance

cc: Mr. BJ Kristensen – WDEQ/LQD Permit Coordinator