

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

TO: Mr Lear

FROM: Florida Pwr & Light Co
Miami, Fla
R E Uhrig

DATE OF DOCUMENT: 4-19-76

DATE RECEIVED 4-22-76

LETTER
 ORIGINAL
 COPY

NOTORIZED
 UNCLASSIFIED

PROP INPUT FORM

NUMBER OF COPIES RECEIVED
one signed

DESCRIPTION

Ltr furnishing info concerning liquid penetrant and ultra-sonic examinations of safe end welds testing during the next refueling outage during the spring of 1976.....

ENCLOSURE

PLANT NAME: Turkey Point #4

SAFETY

FOR ACTION/INFORMATION

ENVIRO

4-28-76 ehf

ASSIGNED AD :

BRANCH CHIEF :

PROJECT MANAGER:

LIC. ASST. :

Lear (5)

Elliot

Parrish

ASSIGNED AD :

BRANCH CHIEF :

PROJECT MANAGER :

LIC. ASST. :

INTERNAL DISTRIBUTION

REG FILE

NRC PDR

I & E (2)

OELD

GOSSICK & STAFF

MIPC

CASE

HANAUER

HARLESS

SYSTEMS SAFETY

HEINEMAN

SCHROEDER

ENGINEERING

MACCARY

KNIGHT

SIHWEIL

PAWLICKI

PLANT SYSTEMS

TEDESCO

BENAROYA

LAINAS

IPPOLITO

OPERATING REACTORS

STELLO

OPERATING TECH

EISENHUT

SHAO

BAER

SCHWENCER

GRIMES

SITE SAFETY & ENVIRO

ANALYSIS

DENTON & MULLER

ENVIRO TECH

ERNST

BALLARD

SPANGLER

SITE TECH

GAMMILL

STEPP

HULMAN

SITE ANALYSIS

VOLLNER

BUNCH

J. COLLINS

KREGER

EXTERNAL DISTRIBUTION

LPDR: Miami, Fla

TIC

NSIC

ASLB

ACRS 16 HOLDING/SENT

NATL LAB

REG. V-IE

LA PDR

CONSULTANTS

TO LA Parrish

BROOKHAVEN NATL LAB


ULRIKSON(ORNL)

CONTROL NUMBER

4075



.....



April 19, 1976
L-76-164

Director of Nuclear Reactor Regulation
Attn: Mr. George Lear, Chief
Operating Reactors Branch #3
Division of Operating Reactors
U. S. Regulatory Commission
Washington, D. C. 20555



Dear Mr. Lear:

Re: Turkey Point Plant Unit No. 4
Docket No. 50-251
NRC Letter of May 2, 1975
Reactor Vessel Safe End Map

Florida Power & Light Company will conduct liquid penetrant and ultrasonic volumetric examinations of the safe end welds of inlet and outlet nozzles on Turkey Point Unit 4 as follows:

- (1) Liquid penetrant examinations of all six safe end welds. The extent of examination coverage will be dependent on the radiation levels and/or accessibility.
- (2) Ultrasonic volumetric examinations of the upper-half of all six safe end welds. The extent of this examination coverage is dependent on radiation levels and accessibility.

The examinations will be performed in accordance with the requirements of the ASME Code, Section XI (through Winter 1970), pursuant to the provisions of IS-244.

These examinations will be performed during the Spring 1976 refueling outage as recommended in your letter of May 2, 1975.

Very truly yours,

for Robert E. Uhrig
Robert E. Uhrig
Vice President

GEL/hlc

cc: Jack R. Newman, Esq.
Mr. Norman C. Moseley

4025

