

**NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL  
(TEMPORARY FORM)**

CONTROL NO: 9630  
FILE: \_\_\_\_\_

FROM: Florida Power & Light Co. Miami, Fla. 33101 R. E. Uhrig		DATE OF DOC 9-8-75	DATE REC'D 9-11-75	LTR XX	TWX	RPT	OTHER
TO: Mr. Roger Boyd		ORIG 1 signed	CC	OTHER	SENT NRC PDR <u>XX</u>		SENT LOCAL PDR <u>XX</u>
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-251		

DESCRIPTION: Ltr furnishing results of inspection of safety related hydraulic pipe restraints located outside of the containment...

ENCLOSURES:  
  
**DO NOT REMOVE**  
**ACKNOWLEDGED**

PLANT NAME: Turkey Pt. Unit 4

**FOR ACTION/INFORMATION**      DHL      9-13-75

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies	REID (L) W/ COPIES
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies	
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPIES W/ Copies	
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	LPM W/ Copies	

**INTERNAL DISTRIBUTION**

<u>REG FILE</u> NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE GIAMBUSSO BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR FILE & REGION (2) MIPC	<u>TECH REVIEW</u> SCHROEDER MACCARY KNIGHT PAWLICKI SHAO STELLO HOUSTON NOVAK ROSS IPPOLITO TEDESCO J. COLLINS LAINAS BENAROYA VOLLMER	DENTON GRIMES GAMMILL KASTNER BALLARD SPANGLER  <u>ENVIRO</u> MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR  HARLESS	<u>LIC ASST</u> R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. RUSHBROOK (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L) M. DUNCAN (E)	<u>A/T IND.</u> BRAITMAN SALTZMAN MELTZ  <u>PLANS</u> MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON
--	--	---	---	--

**EXTERNAL DISTRIBUTION**

✓ - LOCAL PDR Miami, Fla.  
1 - TIC (ABERNATHY) (1)(2)(10) - NATIONAL LABS \_\_\_\_\_  
1 - NSIC (BUCHANAN)      1 - W. PENNINGTON, Rm E-201 GT  
1 - ASLB      1 - CONSULTANTS  
1 - Newton Anderson  
4/6 ACRS \_\_\_\_\_/SENT      NEWMARK/BLUME/AGBABIAN

1 - PDR-SAN/LA/NY  
1 - BROOKHAVEN NAT LAB  
1 - G. ULRIKSON ORNL

*miss 4*  
*TBB*







FLORIDA POWER & LIGHT COMPANY

September 8, 1975

L-75-430

Regulatory Docket File




Mr. Roger Boyd, Acting Director  
Division of Reactor Licensing  
Office of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Dear Mr. Boyd:

Re: Turkey Point Unit No. 4 - Docket No. 50-251  
Inspection of Safety Related Hydraulic Pipe  
Restraints Located Outside the Reactor Containment

The subject inspection was completed on August 22, 1975, in accordance with the continuing requirements of the Directorate of Licensing letter dated November 8, 1973. The inspection showed that all restraints were in an operable condition.

Very truly yours,

  
Robert E. Uhrig  
Vice President

REU:MAS:nch

cc: Mr. Norman C. Moseley  
Jack R. Newman, Esquire

9630

9630

40