

CHAIRMAN Resource

From: Tom Gurdziel <tgurdziel@twcny.rr.com>
Sent: Thursday, December 06, 2018 8:37 AM
To: BarclaW@assembly.state.ny.us
Cc: CHAIRMAN Resource
Subject: [External_Sender] FW: Event Number 53778 at Exelon/FitzPatrick

From: Tom Gurdziel [mailto:tgurdziel@twcny.rr.com]
Sent: Thursday, December 06, 2018 8:18 AM
To: Holden, Tammy L:(GenCo-Nuc) (Tammy.Holden@exeloncorp.com)
Cc: Lyon, Jill:(NMP) (jill.lyon@exeloncorp.com); 'Ed Stronski'; Bridget Frymire (bridget.frymire@dps.ny.gov); 'Screnci, Diane'
Subject: Event Number 53778 at Exelon/FitzPatrick

Hello Tammy,

I would have expected that low service air pressure would not affect the plant's instrument air system, but that is not what I am reading. Also, I get the feeling that back- up air compressors did not automatically start on the loss of instrument air pressure.

Is this event report presented correctly? Was the Standby Gas system supposed to start automatically?

Thank you,

Tom



Virus-free. www.avast.com