



General Offices: 212 West Michigan Avenue, Jackson, Michigan 49201 • Area Code 517 788-0550

March 25, 1975

REGULATORY DIVIDED THE COPM

Mr. Angelo Giambusso
Director of Reactor Licensing
US Nuclear Regulatory Commission
Washington, DC 20555

Dear Mr. Giambusso:

Re: Docket 50-255 License DPR-20 Palisades Plant

Additional Eddy Current

Test Information

During a telephone conversation on Tuesday, March 11, 1975, a member of your staff requested additional information with regard to our March 10, 1975 submittal concerning eddy current testing performed during February 1975.

This information was delivered to your staff on March 13, 1975 and is transmitted, attached to this letter, to formally document our responses. The attached items are:

- Table 1 Palisades "A" Steam Generator Eddy Current Test Results
- Table 2 Palisades "B" Steam Generator Eddy Current Test Results
- Table 3 Tubes Plugged as Part of the February 1975 Palisades "A" Steam Generator Inspection
- Table 4 Tubes Plugged as Part of the February 1975 Palisades "B" Steam Generator Inspection
- Table 5 Tubes with an indication  $\geq$  50% which, when averaged with additional readings, were below 50% and remain in service following the February 1975 Palisades "A" steam generator inspection.
- Table 6 Tubes with an indication  $\geq$  50% which, when averaged with additional readings, were below 50% and remain in service following the February 1975 Palisades "B" steam generator inspection.

Yours very truly,


Ralph B. Sewell

Nuclear Licensing Administrator

Jeph & Oliver

DAB/ce

CC: JGKeppler, USNRC



GOPY

General Offices: 212 West Michigan Avenue, Jackson, Michigan 49201 • Area Code 517 788-0550 February 3, 1975

Mr. J. G. Keppler Regional Director Directorate of Regulatory Operations Region III US Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137 Re: Docket 50-255 License DPR-20 Palisades Plant UE-74-3

Dear Mr. Keppler:

This letter is written to confirm previous discussions with members of your staff and to close out the possible loss of special nuclear material (SNM) as reported to you by Mr. R. B. DeWitt's TWX of January 7, 1975.

The TWX dated January 7, 1975 transmitted a chronological listing of events regarding the possible loss of an out-of-core fission chamber containing approximately 1.7 grams of enriched uranium. This chronological listing started with the date of shipment of the fission chamber and included the efforts by Consumers Power Company to locate the fission chamber as it had not arrived at the plant in the expected time frame. The TWX concluded that the fission chamber was definitely lost.

On January 9, 1975, two days after submittal of the TWX, the fission chamber arrived at the Palisades Plant. At that time, Consumers Power Company again attempted to trace its routing in an effort to preclude a similar recurrence. We have drawn the following major conclusions with respect to the shipment:

- 1. Emery Air Freight acknowledged receiving the fission chamber on December 4, 1974 in Cleveland, Ohio.
- 2. The fission chamber was shipped from Cleveland to Chicago O'Hare on about December 11, 1974. It is not clear what the status of the fission chamber was between December 4, 1974 and December 11, 1974.
- 3. The fission chamber remained at O'Hare Airport (apparently in the custody of Emery Air Freight) until December 31, 1974. On December 31, 1974, the fission chamber was received by Associated Truck Lines at their Chicago terminal.



Loma (1)

Mr. J. G. Keppler Palisades Plant February 3, 1975

4. The fission chamber left the Associated Truck Lines terminal in Chicago on January 2, 1975 and was shown to have arrived in the Benton Harbor terminal of Associated Truck Lines on January 3, 1975.

5. The shipment remained in the Associated Truck Lines Benton Harbor terminal until delivered to Palisades on January 9, 1975.

The quantity of SNM involved is nearly negligible. (Less than 0.5 gram is defined as negligible.) Even so, fission chambers are important to the operation of the Palisades reactor. The experience gained with this shipment will be taken into account when procuring fission chambers in the future.

This report has been classified as Unusual Event 74-3 in the Palisades Plant reporting system for purposes of formally documenting the event.

Yours very truly,

Ralph B. Sewell (Signed)

RBS/mel

Ralph B. Sewell Nuclear Licensing Administrator

CC: Directorate of Regulatory
Operations, Washington, DC
Directorate of Licensing,
Washington, DC