



Robert E. Schuetz
Columbia Generating Station
P.O. Box 968, PE23
Richland, WA 99352-0968
Ph. 509-377-2425 | F. 509-377-4674
reschuetz@energy-northwest.com

February 25, 2019
GO2-19-022

10 CFR 72.44

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555-0001

Subject: **COLUMBIA GENERATING STATION, DOCKET NO. 72-35;
INDEPENDENT SPENT FUEL STORAGE INSTALLATION,
2018 ANNUAL EFFLUENT RELEASE REPORT**

Dear Sir or Madam:

In accordance with 10 CFR 72.44(d)(3), Energy Northwest hereby submits the Independent Spent Fuel Storage Installation (ISFSI) Annual Effluent Release Report for calendar year 2018.


By design, the seal welded storage canister of the Holtec International Corporation's HI-STORM Cask System used at Columbia Generating Station does not have any radioactive material effluents. The seal welded storage system design provides assurance that there are no radioactive effluent release pathways from the storage casks.

This letter documents that there were no radioactive effluents discharged or released from the Columbia Generating Station ISFSI and, therefore, there is no ISFSI-specific data to report for calendar year 2018.

There are no commitments being made to the NRC by this letter. Should you have any questions, please contact Mr. S.A. Nappi, Regulatory Compliance Supervisor, at (509) 377-4598.

Executed this 25 day of February, 2019.

Respectfully,



R.E. Schuetz
Vice President, Operations

cc: NRC RIV Regional Administrator
NRC NRR Project Manager
NRC Sr. Resident Inspector – 988C
NRC Director, Division of Spent Fuel Management, NMSS
C Sonoda – BPA/1399
WA Horin – Winston & Strawn
JO Luce – EFSEC
AW Conklin – DOH
M Priddy – DOH
L Albin – DOH
C Stewart – ANI