

rev 1-15-97

Leak Test Certificate

To: Attn: Dick Barnett
East Jordan Iron Works
P O Box 439
East Jordan MI 49727

Date: February 9, 1996
Ref: PO# GM260131
KR Job No: K32749 S/O 3227 & 9656
Kit Rec'd Ja. 17, 1996

This certifies that each source housing listed below was tested for leakage and/or contamination and the sample(s) analyzed in accordance with approved procedures.

This further certifies that less than 0.000071 uCi of contamination was found on each sample (less than 0.005 uCi is acceptable).

The source capsule isotope is: CS-137

CERTIFIED: *Lee Gleba*
By: Lee Gleba
Title: Field Service Administrator

ANALYZED:
By: Matt Fay
Title: IHR Supervisor
Date: January 22, 1996

Asset #
1429
1358

Leak Test S/N:	Source Holder Manufacturer	Source Holder Model No.	Source Holder Serial No.	Activity (mCi)	Date of Meas.	Date Collected	Collected By
54736	Kay-Ray	7064P	12276 <i>Lower</i>	5,000	N/A	1-5-96	Nick Moes
54739	Kay-Ray	7064P	S95B0702 <i>Upper</i>	5,000	N/A	1-4-96	Nick Moes

Kay-Ray/Sensall, Inc.
1400 Business Center Drive
Mount Prospect, IL 60056-6063 USA
Tel 1 (708) 803-5100

Kay-Ray/Sensall

FISHER-ROSEMOUNT Managing The Process Better.

Leak Test Certificate

To: Attn: Safety Department
East Jordan Iron Works
P O Box 439
East Jordan MI 49727

Date: October 7, 1997
Ref: PO#69278166
KR Job No: S/O 9656 & 3227
KSI Lic No: IL-01010-03

This certifies that each source housing listed below was tested for leakage and/or contamination and the sample(s) analyzed in accordance with approved procedures.

This further certifies that less than 0.005 uCi of contamination was found on each sample (less than 0.005 uCi is acceptable).

The source capsule isotope is: CS-137

CERTIFIED: 

By: Lee Gleba
Title: Field Service Administrator

ANALYZED:

By: Mike Allred
Title: Assistant RSO
Date: October 7, 1997

<u>Leak Test S/N:</u>	<u>Source Holder Manufacturer</u>	<u>Source Holder Model No.</u>	<u>Source Holder Serial No.</u>	<u>Activity (mCi)</u>	<u>Date of Meas.</u>	<u>Date Collected</u>	<u>Collected By</u>
57018	Kay-Ray	7064P	S95B0702	5,000	N/A	9-29-97	Dick Barnett
57019	Kay-Ray	7064P	12276	5,000	N/A	9-29-97	Dick Barnett

Song, Taehoon

From: Kennedy, Erin
Sent: Tuesday, April 02, 2019 2:40 PM
To: Song, Taehoon; Pavon, Sandy; Sandrik, Lauren
Cc: Tomczak, Tammy
Subject: Additional Information for License Termination
Attachments: KayRay Leak Tests.pdf

Good Afternoon Guys,

Please add the attached document to ADAMS.

East Jordan Iron Works

LN 21-13462-03

DN 030-37892

CN ~~6114091~~

611215 FT.

Thank you!

Erin

From: Ted Rundblad [mailto:Ted.Rundblad@ejco.com]
Sent: Tuesday, April 02, 2019 2:31 PM
To: Kennedy, Erin <Erin.Kennedy@nrc.gov>
Subject: [External_Sender] RE: Additional Information for License Termination

Erin,
Here are the scans we discussed.
I hope this helps.
Let me know if you need anything else.
Thank you for helping.
Ted Rundblad

Ted Rundblad
Manufacturing Manager
Office: [231.536.4553](tel:231.536.4553)

From: Kennedy, Erin <Erin.Kennedy@nrc.gov>
Sent: Tuesday, April 2, 2019 2:10 PM
To: Ted Rundblad <Ted.Rundblad@ejco.com>
Subject: Additional Information for License Termination

External Email

Good Afternoon Ted,

Please give me a call in my office when you have a chance or you can email me if that is more convenient.

Thanks,

Erin Kennedy

U.S. Nuclear Regulatory Commission, Region III

Health Physicist- Materials Licensing

Email: erin.kennedy@nrc.gov

Office: 630-829-9876