NRC FORM 591M PART 1 (07-2012)*			U.S. NUCLEAR REGU	LATORY COMMISSION
10 CFR 2.201 SAF	ETY INSPECTION REPORT	AND COMP	LIANCE INSPECTION	
1. LICENSEE/LOCATION INSPECTED: Passport Systems, Inc. 70 Treble Cove Road N. Billerica, MA 01862 Field Office: Port of Boston, Paul W. Conley Terminal 700 Summer St Boston, MA, 02127		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713		
REPORT NUMBER(S)	2018-001			
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE(S) OF INSPECTION	
070-07022 LICENSEE:	SNM-2016		08/29-30/2018, March 1	9, 2019
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspection. The inspection findings are as follows: X				
Statement of Corrective Actions				
I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.				
Title	Printed Name		Signature	Date
LICENSEE'S REPRESENTATIVE				
NRC INSPECTOR	James Cassata, Ph.D., CHF	>	James Cessata	3/19/2019
BRANCH CHIEF	ARTHER L BUR	147	With the	320/19
*NRC FORM 591M PART 1 (07-2012) (RI Rev. 09/12/2013) G:\WBL Documents\WBL Inspection Records\RSNM-2016.2018-001.591M-Part1.doc				
SUNSI Review Completed By:	JCassata		X Public	X Non-Sensitive