

Central File

50-280

50-281

Vepco

VIRGINIA ELECTRIC AND POWER COMPANY

Surry Power Station
P.O. Box 315
Surry, Virginia 23888

August 6, 1976

00 8/5/76

Director of Regulatory Operations
230 Peachtree Street
Suite 818
Atlanta, Georgia

This is to inform you by telecopy of a Reportable Occurrence that was noted on August 5, 1976 at Surry Nuclear Power Station. A unreviewed safety question was identified by Westinghouse in that an incorrect value for reactor head temperature was used for the safety analysis, which lowers the value of K_d to 1.90.

W. F. Stewart
for T. L. Bacon