

Central File  
50-281

**Veeco**

RD-52-76-2

VIRGINIA ELECTRIC AND POWER COMPANY  
Surry Power Station  
P.O. Box 315  
Surry, Virginia 23888

May 11, 1976

Director of Regulatory Operations  
230 Peachtree Street, N.W.  
Suite 818  
Atlanta, Georgia 30303

This is to inform you by telecopy of a Reportable Occurrence that was noted on May 11, 1976 at Surry Nuclear Power Station. During refueling shutdown on Unit 2 the seventh (top) support plate in "A" steam generator was observed to have areas of distortion and cracking.

*E. M. Sweeney, Jr.*  
E.M. Sweeney, Jr.  
Manager