

Vepco

VIRGINIA ELECTRIC AND POWER COMPANY

Surry Power Station
P.O. Box 315
Surry, Virginia 23883

July 7, 1975

Director of Regulatory Operations
230 Peachtree Street, N. W.
Suite 818
Atlanta, Georgia 30303

This is to inform you by telecopy of an Abnormal Occurrence that was noted on July 6, 1975 at Surry Nuclear Power Station. During full power operation on Unit No. 2, a reactor trip occurred caused by the sudden closure of the trip valve in "B" main steam line followed by the closure of "A" and "C" main steam line trip valves. Testing following the trip revealed that the main steam trip valves in "A" and "C" steam lines would not close. An investigation is currently underway to determine the cause of the malfunction and corrective action to be taken.

E. M. Sweeney, Jr.
E. M. Sweeney, Jr.
Station Manager