

Letter to N. C. Moseley from Virginia Electric and Power Company dated May 14, 1975.

DISTRIBUTION:

H. D. Thornburg, IE

IE:HQS (4)

Office of Standards Development

Central Files

Division of Reactor Licensing (4)

PDR

Local PDR

NSIC

TIC

STATE

50-281

Proy

# Vepco

VIRGINIA ELECTRIC AND POWER COMPANY  
Surry Power Station  
P. O. Box 315  
Surry, Virginia 23883  
May 14, 1975

Director of Regulatory Operations  
230 Peachtree Street, N.W.  
Suite 818  
Atlanta, Georgia 30303

Dear Sir:

This is to inform you by telecopy of an Abnormal Occurrence that was noted on May 13, 1975, at Surry Nuclear Power Station, during the refueling of Unit 2. During the lifting of a fuel assembly, the manipulator crane stopped due to overload. The subject fuel assembly was transferred to the spent fuel pit for inspection. Inspection revealed an apparent small perforation in the fuel clad. Subsequent inspection revealed no additional damage to any assemblies that were adjacent to the moving assembly at the time of the incident.

-----Very truly yours,



E. M. Sweeney, Jr.  
Manager