License No. CPPR-66

ENCLOSURE 1

NOTICE OF VIOLATION

Based on the results of the NRC inspection conducted on March 24-26, 1975, it appears that certain of your activities were not conducted in full compliance with conditions of your AEC Facility License No. CPPR-66 as indicated below:

A. Contrary to 10 CFR Part 50, Appendix B, Criterion V: Welding electrode issue times were not being entered on electrode issue forms WD-3 as required by United Engineers and Constructors Procedure MCP-2-2, Paragraph 3.3.1, for the control of moisture in low-hydrogen electrodes.

This item is a deficiency.