

L79-699 FILE: RR 2 (NP-32-79-10)

August 17, 1979

Docket No. 50-346 License No. NPF-3

Mr. James G. Keppler Regional Director, Region III Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Reportable Occurrence 79-084 Davis-Besse Nuclear Power Station Unit 1 Date of Occurrence: August 6, 1979

Enclosed are three copies of Licensee Event Report 79-084 with a supplemental information sheet which is being submitted in accordance with Technical Specification 6.9 to provide 14 day written notification of the subject occurrence.

Yours truly,

Veroning

Terry D. Murray Station Superintendent Davis-Besse Nuclear Power Station

TDM/SNB/1jk

Enclosure

cc: Dr. Ernst Volgenau, Director Office of Inspection and Enforcement Encl: 40 copies LER 79-084

> Mr. William G. McDonald, Director Office of Management Information and Program Control Encl: 3 copies LER 79-084 2 copies telecopy

784145

THE TOLEDO EDISON COMPANY EDISON PLAZA

SON PLAZA 300 MADISON AVENUE

TOLEDO, OHIO 43652

7908230387