

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION IV 611 RYAN PLAZA DRIVE, SUITE 1000 ARLINGTON, TEXAS 76012

June 29, 1979

In Reply Refer To: Docket No. 50-267/79-12

> Public Service Company of Colorado ATTN: Mr. C. K. Millen Senior Vice President P. O. Box 840 Denver, Colorado 80201

Gentlemen:


This refers to the inspection conducted by Mr. M. W. Dickerson of this office during the period June 12-15, 1979, of activities authorized by NRC Operating License DPR-34, and to his discussion of the findings with members of your staff at the conclusion of the inspection.

Areas examined during this inspection are described in our report, which is enclosed with this letter. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the inspector.

During this inspection it was found that certain of your activities were not conducted in full compliance with NRC requirements, as set forth the Notice of Violation enclosed herewith as Enclosure (1). This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office, within 20 days of your receipt of this notice, a written statement or explanation in reply including: (1) corrective steps which have been taken by you, and the results achieved; (2) corrective steps which will be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved.

In accordance with Section 2.790 of the NRC "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and enclosed inspection report will be placed in the NRC's Public Document Room. If this report contains any information that you or your contractors believe to be proprietary, it is necessary that you make a written application within 20 days to this office to withhold such information from public disclosure. Any such application must

- 852 059



include a full statement of the reasons on the basis of which it is claimed that the information is proprietary, and should be prepared so that proprietary information identified in the application is contained in a separate part of the document. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

G. L. Madsen, Chief, Reactor Operations and Nuclear Support Branch

Enclosures:

1. Notice of Violation

IE Inspection Report No. 50-267/79-12

cc w/enclosures:

D. W. Warembourg, Nuclear Production Manager Fort St. Vrain Nuclear Station P. O. Box 368 Platteville, Colorado 80651

L. Brey, Quality Assurance (Same Address)

852 060