

YANKEE ATOMIC ELECTRIC COMPANY



20 Turnpike Road Westborough, Massachusetts 01581

B.3.1.1
WYR-79-106
WVY-79-105
WMY-79-96

September 17, 1979

United States Nuclear Regulatory Commission
Washington, D. C. 20555

Attention: Office of Nuclear Reactor Regulation
W. P. Haass, Chief, Quality Assurance Branch
Division of Project Management

References: (a) License No. DPR-3 (Docket No. 50-29)
(b) License No. DPR-28 (Docket No. 50-271)
(c) License No. DPR-36 (Docket No. 50-309)
(d) YAEC letter to USNRC, W. P. Haass, Dated September 12, 1979.

Dear Sir:

Subject: Yankee Operational Quality Assurance Program (YOQAP-1-A)

Our letter Reference (d) forwarded to you Revision 7 to the Yankee Operational Quality Assurance Program - YOQAP-1-A. Since the date of transmittal, we have identified an error in the cover letter regarding the changes to this program. The correct statement should read as follows: "The changes are made based upon engineering evaluations of system safety classifications for the Yankee Rowe (License No. DPR-3) and Vermont Yankee (License No. DPR-28) operating nuclear power plants."

We trust this information will eliminate any confusion you may have with respect to this matter. Should you have any questions, please contact us.

Very truly yours,

YANKEE ATOMIC ELECTRIC COMPANY

Robert H. Groce
Licensing Engineer

RTT:dis

973212

7909210276